

TRIAC FANUC - 0 M

INSTRUCTION

MANUAL

Version 11 . 92

WARNING

*WARRANTY ON THIS MACHINE WILL BE
INVALIDATED IF ANY MODIFICATIONS,
ADDITIONAL ANCILLIARY EQUIPMENT IS
FITTED OR ANY ADJUSTMENTS MADE
TO THE CONTROLLING DEVICES
WITHOUT PRIOR NOTIFICATION FROM
DENFORD MACHINE TOOLS LTD.*

INTRODUCTION

THANK YOU FOR YOUR SELECTION AND PURCHASE OF OUR TRIAC FANUC MILLING MACHINE.

THIS MANUAL DESCRIBES THE INSTRUCTIONS AS TO THE INSTALLATION, OPERATION AND PROGRAMMING OF THE TRIAC FANUC MILLING MACHINE, IN ORDER TO USE THE MACHINE TO ITS FULL CAPACITY.

THIS MANUAL IS COMPLEMENTED BY A SERVICE MANUAL CONTAINING:

ROUTINE MAINTENANCE, PARAMETER LISTINGS, DIAGNOSTICS, PLC LISTINGS, ELECTRICAL WIRING DIAGRAMS, SPARE PARTS AND ASSEMBLY DRAWINGS AND TROUBLE SHOOTING.

IN ADDITION TO THESE MANUALS, PLEASE REFER TO THE INSTRUCTION MANUALS OF OUR CONTROL SUPPLIERS FOR DETAILED OPERATING TECHNIQUES.

This page intentionally left blank.

INSTRUCTION MANUAL

- SECTION 1 STANDARD EQUIPMENT SUPPLIED
- SECTION 2 SPECIFICATIONS
- SECTION 3 INSTALLATIONS
- SECTION 4 OPERATIONS
- SECTION 5 CNC APPLICATIONS
- SECTION 6 CUSTOMERS OBSERVATIONS

SECTION INDEX

SECTION 1

- STANDARD EQUIPMENT SUPPLIED 1.0

SECTION 2

- SPECIFICATION 2.0
- MACHINE EXTENT DIAGRAM 2.1
- CAPACITY DIAGRAM 2.2
- SPECIFICATION SHEETS 2.3

SECTION 3

- INSTALLATION 3.0
- INTRODUCTION 3.1
- LIFTING TRIAC 3.2
- LEVELLING TRIAC 3.3
- ELECTRICAL CONNECTIONS 3.4
- AIR CONNECTION 3.5
- PREPARATION OF MACHINE 3.6

SECTION 4

- OPERATION OF TRIAC 4.0
- INTRODUCTION 4.1
- SAFETY PRECAUTIONS 4.2
- CONTROL DESCRIPTION 4.3
- TOOLING 4.4
- START UP PROCEDURE 4.5
- DATUM OF AXES 4.6
- RUN IN PROCEDURES 4.7

SECTION INDEX

SECTION 5

- INTRODUCTION 5.1
- WORD DESCRIPTIONS 5.2
- BASIC MOVEMENTS &
RADIUS COMPENSATION 5.3
- PROGRAMMING INSTRUCTIONS 5.4
- SUBROUTINES & CYCLES 5.5
- EXAMPLES 5.6
- GLOSSARY OF TERMS 5.7

SECTION 6

- CUSTOMERS OBSERVATIONS 6.0

APPENDIX

- TRIGONOMETRY & GEOMETRY
- TABLES OF INFORMATION

This page intentionally left blank.

SECTION 1

STANDARD EQUIPMENT SUPPLIED:

- TRIAC FANUC CNC MILLING MACHINE 1
- TRIAC FANUC INSTRUCTION MANUAL 1
- TRIAC FANUC SERVICE MANUAL 1
- FANUC SERIES OMC MANUALS 1SET

STANDARD EQUIPMENT:

- SET OF KEYS 1
- SET OF METRIC ALLEN KEYS 1
- SET OF MACHINE FUSES 1

COOLANT OPTION ONLY:

- SET OF ALTERNATIVE COOLANT PIPE NOZZLES 1

This page intentionally left blank.


SECTION 2

SPECIFICATION


- MACHINE EXTENT DIAGRAM 2.1
- CAPACITY DIAGRAMS 2.2
- SPECIFICATION SHEETS 2.3

This page intentionally left blank.



2.1 TRIAC FANUC MACHINE EXTENT




2.2 CAPACITY DIAGRAMS




**MOVEMENT OF A.T.C.OVER TABLE
& SPINDLE TRAVEL OVER TABLE**



TEE SLOT SECTION



HEAD POSITION



2.3 SPECIFICATIONS

2.3.1 MACHINE SPECIFICATION

1 STANDARD FEATURES - TRIAC FANUC (ATC)

A)General:

1) Machine dimension list:

Cabinet:

Length:	1000mm (39 1/2")
Width:	1140mm (45")
Height:	2000mm (78 3/4")

2) Weight:

Machine Weight:	340 kg (750 lbs)
-----------------	------------------

B)Capacities:

Table Area: 500 x 160mm (19 1/2" x 6 1/4")

T Slots: 10mm slots

Traverses: X: 290mm

Y: 175mm

Z: 200mm

Maximum feed Rate: 5 m/min

Spindle nose to table top: Max: 275 mm

Min: 75mm

Spindle nose to column: 177mm

Maximum feeding force: 17.6 KN

C)Main Spindle

Drive Motor: Fanuc DC 1 HP

Speed range: 0 - 4000 RPM

Spindle Type: ATC - No 35 INT,
STD R8

Spindle Orientation: Programmable

D) Axis Motors

FANUC AC Digital Servo (Brushless)

Maximum Torque: 7 - 8 NM

E) Tooling

Maximum Tool Diameter: 80mm

Maximum Tool Length: 90mm

F) ATC (Optional)

Number of Stations: 6

Time for Tool Change: 7 Secs

G) Coolant (Cutting Fluid)

Pump Motor: 20 l/min (4.4 G/min)

Tank Capacity: 40. Litres

H) Machine Working Lights

12v AC Halogen Lo-Vo Light

I) Enviromental Conditions

Power Supply: 50/60 HZ 3PH

380/415V 12 Amps

Total Power Consumption: 5 KW

2-3-1 NC CONTROL SPECIFICATION

1 STANDARD FEATURES - FANUC OM MODEL C

A) Controlled Axes

Controlled Axes 3 Axes (X Y & Z)

Simultaneous

Contouring Control

Least input increment

0.001mm (0.00004")

Least command increment

0.001mm

B) Interpolation Functions

Positioning

G00

Linear Interpolation

G01

Multi-quadrant circular

Interpolation

G02, G03

C) Feed Functions

Rapid Traverse

5m/min

Rapid Traverse Override

100%, 50%, 25%, 0%

Manual Pulse Generator

Increments,

0.001/0.01/0.1

Manual Continuous Feed

Cutting Feed Rate

G94 (mm/min),

G95 (mm/rev)

Cutting Feed Rate Clamp

Feed Rate Override

0 to 150% at 10%

increment

Tangential Speed	
Constant Control	
Automatic Acceleration/ Deceleration	Linear for rapid traverse exponential for cutting feed
Dwell G04	0 to 99999.999 sec
Dry Run	
Free Hold	
Reference Point Return	G27, G28 and G29
Exact Stop	G09

D) Spindle Functions

Spindle Speed Command	S-5 Digit Direct RPM
Constant Surface Speed Control	G96 and G97
Spindle Speed Override	50% to 120% at 10% increment

E) Tool Functions

T-Function	2 Digit Tool Number + 2 Digit Offset Numbers
Tool Offset Amount	±6 Digits separate settings of geometry offsets. 16 Pairs in Memory

Tool Radius Compensation	G40, G41 and G42
--------------------------	------------------

Programmable Data	
-------------------	--

Input	G10 Option
-------	------------

Direct input of offset value measured	
---------------------------------------	--

Incremental Offset	
--------------------	--

Counter Input of Offset Amount	
--------------------------------	--

F) Miscellaneous Functions

M-Functions 2 Digits	
----------------------	--

G) Programming Functions

Plane Switching	XY, XZ, YZ
-----------------	------------

Co-ordinate System	
--------------------	--

Setting	G54 - G59
---------	-----------

Inch/Metric conversion	G20 and G21
------------------------	-------------

Decimal Point Programming	
---------------------------	--

Radius Programming on arc	
---------------------------	--

Canned Cycles	G73, G74 G76
---------------	--------------

	and G80-89
--	------------

Program Number	O (EIA code) or
----------------	-----------------

	: (ISO) 4 digits
--	------------------

Program Number Search	
-----------------------	--

Program Name	
--------------	--

Main Program and Sub Programs	
-------------------------------	--

Sequence Number	N 4 Digits
-----------------	------------

Tape Code	EIA (RS-244A)/
-----------	----------------

	ISO(R-804)
--	------------

Input/Output Interface	
------------------------	--

Optional Block Skip	
---------------------	--

Buffer Register	
-----------------	--

Program Stop	M00
--------------	-----

Optional Stop	M01
---------------	-----

Program End	M02 or M30
-------------	------------

Single Block	
--------------	--

Part Program Storage & Editing	
--------------------------------	--

Tape Storage Length	10M (4000 char)
---------------------	-----------------

Registerable Programs	63 Programs
-----------------------	-------------

H) Safety Functions

Emergency Stop	
----------------	--

Software Limits	X,Y and Z
-----------------	-----------

Machine Lock	
--------------	--

Cutting Block Start	
---------------------	--

Interlock	
-----------	--

I) Others

Manual Data Input (MDI)	Keyboard Type
-------------------------	---------------

Software Keys	5 Keys
---------------	--------

9" Monochrome CRT Character Display	
-------------------------------------	--

Self Diagnosis Functions

External Data Input

External Tool Compensation

*Alarm and OperatorMessage Only

Programmable Controller PC-model L

NOTES:

Power Supply 415 Volts 3PH + Neutral

Temperature 0 degrees C to
45 degrees C

Relative Humidity Less than 75%

2.3.2. OPTIONAL EXTRAS

Additional Programmable Memory: Total 320m

Conversation Program with Graphic Functions

Program Input of Offset Data

Cutter Compensation Addition A : TTL 64

Custom Macro A

Pattern Data Input

Graphic Display

Clock Function

Handwheel Intervention

MDI Operation B

Background Editing

Work Co-ordinate System G54 - G59

Program Restart

2nd Auxiliary Function

Tool Life Management

Helical Cutting

Additional Axis Control

Co-ordinate System Rotation

Scaling

Automatic Corner Override

Simultaneous 4 Axis Control

Macro Executer

Reader/Puncher Interface

This page is intentionally blank.

SECTION 3

INSTALLATION

- INTRODUCTION 3.1
- LIFTING 3.2
- LEVELLING 3.3
- ELECTRICAL CONNECTION 3.4
- ACCESS 3.5
- AIR CONNECTION 3.6
- PREPARATION OF MACHINE 3.7

This page is intentionally blank.

3.1 INTRODUCTION

This section describes the correct procedures for installing your TRIAC FANUC Milling machine.

These procedures should be followed precisely to ensure your TRIAC FANUC is not damaged in any way during the installation period


During the installation period the protective coats and coverings applied prior to despatch should NOT be removed.

All installation work should be carried out by qualified personnel.


TRIAC FANUC is a floor mounted milling machine, hence it is important to ensure a level site is prepared.

If in doubt contact DENFORD's Servicing Department for further details.

3.2 LIFTING A TRIAC FANUC



3.3 LEVELING PROCEDURE



The TRIAC FANUC stands on six anti-vibration leveling feet situated at each corner of the machine and also in the electrical cabinet at the rear of the machine. The machine bed is leveled to the cabinet during manufacture hence it is only necessary to ensure that the cabinet is leveled during installation.

FEET LOCATION

Once the coolant tank has been pulled clear of the machine cabinet base, the four feet are accessible through the inside of the cabinet side panels - see diagram on previous page. The two feet on the electrical cabinet are accessible through the main electrical cabinet door at the rear of the machine.

LEVELING

Tools required:- Spirit level, 10mm & 24mm A/F Spanners.

Place the spirit level on the centre of the table parallel to the "T" slots. If the bubble is not aligned adjust as follows:-

Release the locknut on the leveling screw whilst holding the screw stationary with the 10mm spanner. By turning the screw CW the machine can be raised, conversely

turning the screw CCW the machine can be lowered. When the bubble is aligned, turn the spirit level through 90 degrees and again adjust to align the bubble. Re-check for level at the extreme ends of the table. Once the machine is level, tighten the locknuts taking care to hold the screw stationary.


NOTE:- The two feet inside the electrical cabinet should not be used to level the machine and should be adjusted LAST and only to support the electrical cabinet.

ELECTRICAL CABINET

NB. THE ELECTRICAL CONTROL BOX IS INSPECTED THEN SEALED WITH A YELLOW SEAL, IF THIS SEAL IS BROKEN ON DELIVERY INFORM THE SUPPLIERS IMMEDIATELY. THE SEAL SHOULD ONLY BE BROKEN FOR THE INITIAL MAINS POWER CONNECTION.

PUMP CABLE

The coolant pump cable beneath the machine is attached to the machine cabinet by a spring and hook to prevent entrapment when the mobile coolant tank is pulled out to the front of the machine for filling and emptying.



3.4 ELECTRICAL CONNECTION

Cable Needed:-

3 Core + Neutral & Earth, 2.5mm per phase

For U.K Market:-

3 Phase + Neutral 415v 50Hz Current Taken 8 Amps/Phase

For Export Market:-


Contact Denford Servicing Department

Tools Needed:- Wire Strippers, Small Flat Blade Screwdriver


CONNECTION PROCEEDURE:-

- Unlock and open cabinet at rear of machine.
- Mains connection block is located on the panel in the bottom centre
- Feed cable through cable entry as shown on next page.
- Connect separate wires into connection block as shown on next page.


3.4 TRIAC FANUC ELECTRICAL CONNECTIONS




CONNECTION BLOCK





3.5 SERIAL LINK



RS 23 2 SERIAL LINK



3.5 ACCESS POINTS



3.6 AIR SUPPLY UNIT


AIR FILTER REGULATOR AND LUBRICATOR

PRESSURE ADJUSTER

PULL UP TO UNLOCK

PUSH DOWN TO LOCK

Air consumed = ATC : $0.87 \text{ dm}^3/\text{cycle}$
Power Vice : $+0.092 \text{ dm}^3/\text{cycle}$



Maximum pressure for air regulator 9.9 Kg F/cm^2 ($150 \text{ lbs sq}''$)

Operating pressure $100 \text{ lbs sq}''$

Check main supply pressure before adjusting pressure.

3.7 MACHINE PREPARATION

Equipment Required:- Machine slide way oil (See Service Manual Section 1.5), Glass and Perspex Cleaner

On delivery, the machine will have all untreated surfaces within the work area covered with a protective solution.

This is removed using a kerosene base solvent and should be done before any attempt is made to move the slides or operate the machine.

Once the protective coating is removed all untreated surfaces should be covered with a light smear of machine oil (i.e B.P: CS 68).


The protective plastic sheet on the windows is pulled off and the glass and perspex should be cleaned with an anti-static cleaner.

COOLANT TANK

The coolant tank breaks down into four component parts :-

1. The Ferrous filter tray
2. The Non - Ferrous filter tray
3. The Main Body tank
4. The Pump Filter Tank Base.

Trays 1 and 2 lift clear (separately) of the main body tank, the main body tank can then be




separated from the base by removing the six screws.


COOLANT DRAINING

There are basically two methods of draining the coolant tank :-

1. With the coolant tank still in place beneath the cabinet base, place the drum or container which is to hold the drained off coolant as near to the machine cabinet as possible. Angle the coolant nozzle(s) into the drum and switch on the coolant flow (see diagram below). When the coolant ceases to flow, switch off the coolant and pull out the tank from beneath the cabinet (front or rear depending on the cabinet model). The tank can then be separated as in the diagram on the previous page and the remainder of the coolant removed from the base.



2. With the coolant tank still in place beneath the cabinet and with the coolant switched off, remove the coolant delivery pipe from the pump by removing the clip. Place a pipe of the same size over the pump nozzle which you have just removed the delivery pipe from, clamp with the same clip and place the other end in a drum or container, then switch on the coolant pump to drain the coolant into the drum. When the coolant ceases to flow, switch off the coolant pump, pull out the coolant tank from beneath the cabinet. The tank can then be separated as in (1) above. Ensure delivery pipe is reconnected to pump after the draining operation is completed.



SECTION 4

OPERATION

- INTRODUCTION 4.1
- SAFETY PRECAUTIONS 4.2
- CONTROL DESCRIPTIONS 4.3
- TOOLING 4.4
- START UP PROCEDURE 4.5
- DATUM OF AXES 4.6
- RUN IN PROCEDURE 4.7

4.1 INTRODUCTION

This operation section of the manual is intended to allow a competent machinist to get started on TRIAC FANUC.

In 4.3 the control description part, each button is identified in turn with a brief description of what it is intended to do. For further details, the FANUC Manuals supplied and Section 5 of this Manual should be consulted.

This section also covers the type of tooling used on TRIAC FANUC and describes how to mount different tools.

The final part of this section goes through the correct procedure for starting up TRIAC FANUC. The operator should ensure he/she reads the start up procedures thoroughly and adhere to them whenever turning on the machine.

4.2 SAFETY PRECAUTIONS

This machine has safety devices in order to protect the operator and machine from any unexpected accident.

1. Tidyness

- Do not place objects on top or around the machine so that it interferes with guards or the operation of the machine.
- Operate the machine in environment conditions which are suitable for CNC Control.

2. Power Source

- Ensure correct cable for power source is used. (See Section 3.4)
- When power fails turn off the isolator (found on the left hand side of the machine cabinet) immediately.
- When leaving TRIAC FANUC at the end of a shift ensure power is turned off.
- Ensure that TRIAC FANUC is isolated before any maintenance of the machine is carried out.

3. Lubricating Oil and Inspection

- For lubrication, please refer to maintenance Section, (See Service Manual Section 1.5)
- Check oil reservoir daily,
- Check state of slideway lubrication each day. The machine is fitted with an auto-lubricating system. Ensure the reservoir is topped up regularly when indicated by the low-lube indicator situated at base of LO VO lamp.

4. Hints on Safety Operation

- When operating the machine, wear clothing suitable for safe operation.
- Secure workpiece firmly on table
- Only operate the machine after raising all safety screens.
- DO NOT lower safety screens during operation.
- Before starting daily operation, run machine for a few minutes to warm up.


-
- It is very dangerous to handle swarf, the tool nose and any rotating part of the machine. Never, try to remove the swarf during operation.
 - After setting tools, perform trial cutting by manual operation.
 - Use a tool offset function effectively in order to avoid a machining failure.
 - When cleaning the machine and its attachments, be sure to stop machine operation.
 - Do not forget to inspect and clean the machine and NC unit.
 - Do not operate the machine with the power control box open.
 - When opening the doors of the electrical cabinet, turn OFF the isolator in advance.
 - When an emergency stop is required, operate the EMERGENCY STOP switch on the operation panel.

4.2 SAFETY DEVICES

This machine is equipped with the following safety devices for the safety of the operator and protection of the machine.

NAME	LOCATION
● MOTOR OVERLOAD	INSIDE ELECTRICAL CABINET
● AUTOMATIC SERVO	INSIDE ELECTRICAL CABINET
● EMERGENCY STOP SWITCH	OPERATION PANEL
● ISOLATOR	OUTSIDE ELECTRICAL CABINET
● LIMIT SWITCES	ALL AXIS TRAVELS

4.3 FANUC DISPLAY SCREEN AND DATA INPUT PANEL



- 1) Display Screen
- 2) Software controlled keys used to select option shown above each key.
- 3) Input Panel

4.3 FANUC DATA INPUT PANEL (DIAGRAM ON NEXT PAGE)

- RESET Resets any alarm messages. Resets program to start in edit mode.
- ALPHA/NUMERIC PAD Inputs character expected by controller when inputting program. Multi character keys toggle between characters shown
- CURSOR Moves cursor through program element by element in defined direction
- PAGE Moves cursor through program page by page in defined direction.


SELECTION KEYS EACH HAVING SEVERAL PAGES

- POS Axis positions
- PRGRM Program selection screen
- MENU Tool offset and macro variables OFFSET (Macros optional)
- DGNOS Machine diagnostics and parameters PARAM
- OPR Displays operator and machine alarm messages. ALARM (May also display operators panel on OM Model A Controllers)
- AUX Graphics (Optional) GRAPH


EDITING KEYS

- ALTER Alters addresses
- INSRT Inserts addresses. (Also used to initialise new programs)
- DELET Deletes addresses.
- / ; # E.O.B. - characters shown are toggle EOB operated when editing.
- CAN Cancels an address. (Before EOB is executed)
- INPUT Allows input of data, tool offsets etc. Allows input of a program from an external source when in edit mode.
- OUTPUT/START Allows output of a program to an external unit. START (May also start cycle on OM Model A)

4.3 FANUC DATA INPUT PANEL




4.3 FANUC OPERATORS PANEL




- 1) Program Protection key Switch.
- 2) Automatic Operation Panel.
- 3) Manual Operation Panel.
- 4) Emergency Stop and Manual Feed Override

4.3 PROGRAM PROTECTION UNIT



- ON - Protects program from tampering or accidental erasure.
- OFF - Allows full program editing

4.3 AUTOMATIC OPERATION PANEL



PROGRAM SOURCE

- AUTO - Select to run program.
- EDIT - Select to edit program.
- MDI - Select to manually key in G & M Codes out of program mode.


OPERATION SELECT

- SINGL BLOCK - Allows single step execution of program.
- BLOCK DELETE - Select in edit mode to ignore block when running program (Activates \ in front of block)
- OPT STOP - Used in conjunction with M01 to optionally stop program.
- DRY RUN - Runs program through at jog feed rate.
- PRG TEST - Runs program through ignoring all M codes.
- AXIS INHIBT - Runs program through with axes locked.

EXECUTION

- CYCLE START - Starts program.
- CYCLE STOP - Stops program.
- PRG STOP - Stops program at end of current block.

4.3 FANUC MANUAL OPERATION PANEL



- HOME - Zeros machine around its own reference points.
- JOG - Moves axes around at feeds as set on override.
- INC JOG - Moves axes at 0.001, 0.01, 0.1, 1 Increments.
- MPG - Manual Pulse Generator (Electronic Handwheel Control)

-
- TEACH - Inputs actual machine position into program.
 - X 1) - Multiplier selection for handwheel control MPG or
 - X 10) INC JOG mode
 - X 100)
 - X 1K - Multiplier for INC JOG mode
 - SPDL DEC - Spindle Decrease (Override of SPDL 100%), -10 %.
 - SPDL 100% - Reverts spindle speed back to programmed value.
 - SPDL INC - Spindle increase (Override of SPDL 100%), +10%.

AXIS/DIRECTION - Press either JOG or MPG to operate.

- -X - Movement in -X direction
- +X - Movement in +X direction
- -Y - Movement in -Y direction
- +Y - Movement in +Y direction
- -Z - Movement in -Z direction
- +Z - Movement in +Z direction
- -4th - Movement in -4th direction
- +4th - Movement in +4th direction
- TRVRS - Rapid Traverse (toggle switch)


SPINDLE

- CW - Spindle movement clockwise
- STOP - Spindle Stop.
- CCW - Spindle movement counter clockwise

COOLANT

- CLNT ON - Coolant ON
- CLNT OFF - Coolant OFF
- CLNT AUTO - Coolant operated by program

4.3 EMERGENCY STOP AND MANUAL FEED OVERRIDE




- Manual override of program feed and rapid traverse.
- Override of axis direction feed rates.

EMERGENCY STOP

- Cuts all power to drives.

4.3 OPERATORS PANEL



Control

- 1) Green button to start control system.
- 2) Red button to close down control system.

A.T.C.

- 3) Spindle clamp operator, push to open, release to close.
- 4) Carousel index clockwise by one position.
- 5) Carousel index counter clockwise by one position.

Limit Switch

- 6) Manual limit switch override.

Handwheel

- 7) Manual pulse generator. Manual movements of X,Y and Z axes when in handwheel mode.


Clockwise : Positive direction

Counter clockwise : Negative direction


4.4 TRIAC FANUC TOOL CHANGING (MANUAL)

UNLOADING TOOL

DRAWBAR (7/16" UNF)
TO RELEASE R8 ARBOR
ONLY



LOADING TOOL



4.4 TRIAC FANUC TOOL CHANGING (PNEUMATIC DRAWBAR)

To change the tool when using a pneumatic drawbar use the following procedure:

- 1) Stop spindle.
- 2) Use spindle clamp operator button on operators panel (See diagram section 4.3) to release tool. Press to release.
- 3) Replace old tool with new and release spindle clamp operator button to hold tool in spindle.

4.4 TRIAC FANUC TOOL CHANGING (A.T.C.)

If the machine is fitted with an automatic tool changer then use the following procedure to change tools:

- 1) Change to M.D.I. mode.
- 2) Use M06 command followed by the tool number corresponding to the desired tool in the carousel.

4.5 TRIAC FANUC START UP PROCEDURE

The start up procedure for TRIAC FANUC is as follows:-

- Switch ON isolator found at rear of cabinet.
- Switch ON Control, Green button on Operators Panel, No.5 (See diagram Section 4.3)

Wait for screen to display:-

OPERATORS MESSAGE
DENFORD MACHINE TOOLS LIMITED
TRIAC FANUC
Serial _____
Date _____
P.L.C. _____

4.6 DATUM OF AXES

DATUM AXES AS FOLLOWS:-

- Start up machine with P and CAN depressed when switching on power.(Special case , use only on delivery of machine.).
- Jog off limits.
- Press Home button on FANUC Manual Operations Panel.
- Press "+ X" button on FANUC Manual Operations Panel and wait for table to come to a stand still.
- Press "+ Y" button on FANUC Manual Operations Panel and wait for table to come to a stand still.
- Press "+ Z" button on FANUC Manual Operations Panel and wait for spindle head to come to a stand still
- Press "POS" button on FANUC Input Panel.
- Press Page arrow pointing downwards until page showing absolute, relative and machine positions is displayed.
- Ensure the X,Y and Z values are ZERO on "Machine" read out.

The machine is now ready for use.

NOTE:-

If X,Y and Z values are not ZERO seek expert advice.

4.7 RUN IN PROCEDURES

Before working on TRIAC FANUC for the first time it is important that the spindle is "RUN-IN" for a time.

This should be done to the following procedure:-

SPEED	TIME
● 500 RPM	15 MINUTES
● 1000 RPM	10 MINUTES
● 2000 RPM	10 MINUTES

Hence TRIAC FANUC is run in for a total of 35 Minutes

To run in TRIAC FANUC follow the procedure on the next page.

STARTING SPINDLE ON TRIAC FANUC

To " RUN IN " TRIAC FANUC follow the following procedure:

- 1. Select M.D.I. MODE on the automatic operations panel.(See section 4.3)
- 2. Press the PRGRM Key on the data input panel. (See section 4.3)
- 3. Press PAGE ↓ UNTIL the M.D.I. Screen is displayed.
- 4. Press M 03 INPUT
- 5. Press S 500 INPUT
- 6. Press CYCLE START

NOTE:

ENSURE SPDL 100% IS ACTIVATED ON OPERATION PANEL.

To change speed:

- 1. Press S 1000 INPUT (the value after the S code should be changed to the numbers given on the previous page after the correct time interval).
- 2. Press CYCLE START

To stop spindle:

- 1. Press M 05 INPUT
- 2. Press CYCLE START

SECTION 5

CNC APPLICATIONS

- WORD DESCRIPTIONS 5.1
- BASIC MOVEMENTS AND RADIUS
COMPENSATION 5.2
- PROGRAMMING INSTRUCTIONS 5.3
- SUBROUTINES AND CYCLES 5.4
- EXAMPLES 5.5

This page is intentionally blank.

MANUAL PROGRAMMING

The first step in manual programming is to decide upon a machining method to achieve the specified shape, size and finish. This takes the form of a planning sheet which would be very similar to that for the same operation on a conventional miller.

Number of passes, tools, depths of cut, feeds and speeds are all included, and additionally, setting distances for tools, from a datum in each plane, are required.

The programmer then uses all this information to complete the program sheet, which is written in rows of information, each row containing a block of tape data.

In writing the program, the programmer must perform calculations to allow for tool point radius when machining chamfers, tapers or arcs, when work surface programming is not active.

It is also necessary to calculate values for 3 further 'address' letters 'I', 'J' and 'K' when machining parts of a circle. These values represent the arc centre, and enable the interpolator to issue movement instructions to each axis.

When complete, the program sheet is typed into the machine memory and then recorded on a cassette tape.

This page is intentionally blank.

SUMMARY OF TYPICAL ADDRESS CHARACTERS

N	SEQUENCE NUMBER
X	PRIMARY MOTION 'X' AXIS
Y	PRIMARY MOTION 'Y' AXIS
Z	PRIMARY MOTION 'Z' AXIS
G	PREPARATORY FUNCTIONS
I	INCREMENTAL DISTANCE PARALLEL TO 'X' AXIS
J	INCREMENTAL DISTANCE PARALLEL TO 'Y' AXIS
K	INCREMENTAL DISTANCE PARALLEL TO 'Z' AXIS
R	RADIUS
M	MISCELLANEOUS FUNCTIONS
T	TOOL NUMBERS
S	SPINDLE SPEEDS
F	FEED RATES

This page is intentionally left blank

SECTION 5.2

WORD DESCRIPTIONS

- PART PROGRAMMING WORDS AND GENERAL RULES 5.2.1
- TAPE FORMAT SPECIFICATION 5.2.2
- WORD DETAILS 5.2.3

5.2.1 PART PROGRAMMING WORDS

In numerical control, a word by definition is considered to be a specific command or piece of data in a part program block. A word begins with an alphabetic character (the word address) and is followed by a value of one or more numerical digits.

The words on the following pages are used in part programming for the FANUC OM.

GENERAL RULES

For words which are programmed in a decimal point format, the OM assumes leading zero suppression, when the decimal point is not programmed.

For words which are not programmed with a decimal point,

Leading Zero suppression is active.

Example:

- N10 is N0010
- G1 is G01

The number of numerical digits in a word is established. See Tape Format Specification.

The position of the decimal point for display is also established, See Tape Format Specification.

Leading or trailing zeros may be programmed in all words to clarify intention and simplify readability.

Program all minus (-) signs.

5.2.2 TAPE FORMAT SPECIFICATION

This specification is to describe the digit field which may follow each letter address given here. The meaning of the two digits following a letter address shows the implied position of the decimal point.

Example : X ± 5.3

This implies that X can be plus or minus with up to 5 digits before the decimal point and up to 3 digits after the point.

a) The standard Tape Format Specification with the feedrate in mm/rev (G95) is:-

/1 :4	N4	G2	X/U ± 4.3
Y/V ± 4.3	Z/W ± 4.3		
I ± 4.3	J ± 4.3	K ± 4.3	
R4.3	F3.4	P7	Q7
S4	T4	M2	

b) For Programming Feedrate in mm/min (G94) the Format is:-

F5.0

IMPERIAL AND METRIC

When commanding a dwell (G04) in seconds the Format for the X, U or P words in Imperial or Metric Mode is:-

X4.3	U4.3	P4300
------	------	-------

5.2.3 WORD DETAILS

Although the Control will, in general, accept part programming words in any sequence, it is recommended that the word order for each block is used:-

/ N.G. X or U.Y or V.Z or W.I.K.F.S.T.M.

/ **Block**

A slash as the first character in a block allows that block to be ignored when the Block Delete pushbutton is activated.

Example: /N1020 M00

O: Program Number

The : followed by a 4 digit numerical value is used to assign a program number.

N : Sequence Number

The N word may be omitted. When programmed, the sequence number following the N address is a four digit numerical value and is used to identify a complete block of information. Although ascending, descending, or duplicate numbering is allowed, it is best to program in ascending order in increments of 10. This allows for future editing and simplified sequence number search.

G : Preparatory Command

The two digit G command is programmed to set up the control to perform an automatic machine operation. A full list of G codes are given. One G word from each modal group and one non modal G word can be programmed on the same block.

EXAMPLE : Valid N100 G00 G40 G90 G95

Non Valid N100 G00 G40 G41 G90 G95

- G40 & G41 are from the same group.

A retained G word (Modal) from one group remains active

until another G word from the same group is programmed.

One-shot G words (Non-Modal) must be programmed in every block when required.

A power down/up reactivates the G words which are indicated by an asterisk (*). See following pages.

G CODES LISTING FOR DENFORD MILLERS

Group	1	G00	Positioning (Rapid Traverse)
	1	G01	Linear Interpolation (Cutting Feed)
	1	G02	Circular Interpolation/Helical CW
	1	G03	Circular Interpolation/Helical CW
	0	G04	Dwell, Exact Stop
	0	G09	Exact Stop
	0	G10	Data Setting
	0	G11	Data Setting Mode Cancel
*	2	G17	XY Plane Selection
	2	G18	ZX Plane Selection
	2	G19	YZ Plane Selection
	6	G20	Input in inch
	6	G21	Input in mm
	0	G27	Reference Point Return Check
	0	G28	Return to Reference Point
	0	G29	Return from Reference Point
	0	G30	2nd Reference Point Return
	0	G31	Skip Function
	1	G33	Thread Cutting
	0	G39	Corner Offset Circular Interpolation
	7	G40	Cutter Compensation Cancel
	7	G41	Cutter Compensation Left
	7	G42	Cutter Compensation Right

8	G43	Tool Length Compensation + Direction
8	G44	Tool Length Compensation + Direction
* 8	G49	Tool Length Compensation Cancel
* 11	G50	Scaling Cancel
11	G51	Scaling
* 14	G54	Work Co-ordinate System 1 Selection
14	G55	Work Co-ordinate System 2 Selection
14	G56	Work Co-ordinate System 3 Selection
14	G57	Work Co-ordinate System 4 Selection
14	G58	Work Co-ordinate System 5 Selection
14	G59	Work Co-ordinate System 6 Selection
0	G60	Single Direction Positioning
15	G61	Exact Stop Mode
15	G62	Automatic Corner Override
15	G63	Tapping Mode
* 15	G64	Cutting Mode
0	G65	Macro Call, Macro Command
12	G66	Macro Modal Call
* 12	G67	Macro Modal Call Cancel
16	G68	Co-ordinate Rotation
* 16	G69	Co-ordinate Rotation Cancel
9	G73	Peck Drilling Cycle
9	G74	Counter Tapping Cycle

9	G76	Fine Boring
* 9	G80	Canned Cycle Cancel
9	G81	Drilling Cycle, Spot Boring
9	G82	Drilling Cycle, Counter Boring
9	G83	Peck Drilling Cycle
9	G84	Tapping Cycle
9	G85	Boring Cycle
9	G86	Boring Cycle
9	G87	Back Boring Cycle
9	G88	Boring Cycle
9	G89	Boring Cycle
* 3	G90	Absolute Command
3	G91	Incremental Command
0	G92	Programming of Absolute Zero Point
* 5	G94	Feed per Minute
5	G95	Feed per Rotation
* 10	G98	Return to Initial Point in Canned Cycle
10	G99	Return to R in Canned Cycle

NOTES FOR G CODE LISTING

NOTE 1:


G Codes of 00 group represent those not modal and are effective to the designated block

NOTE 2:

G Codes of different groups can be commanded to the same block infinitely. If more than one G code of the same group are commanded the one commanded latter becomes effective.

Axis Definitions

TRIAC FANUC is a three axis mill. The illustrations show the positive and negative axes, indicating the direction of the tool movement. This is an important concept to understand. Because all programming is done with this in mind, that is all motion programmed is the movement of the tool , not the movement of the table.




X Direction from datum:




- X- Left forward movement of the tool.
- X+ Right forward movement of the tool.

Y Direction from datum:



- Y+ Tool moves away from the operator.
- Y- Tool moves towards the operator.

Z Axis directions:



Incremental Axes (G91 SET)

X Axis Command

The X word is an incremental distance which is used to command a change in position perpendicular to the spindle centre line.




Y Axis Command

The Y Word is an incremental distance which is used to command a change of position away and towards the operator.

Z Axis Command

The Z word is an incremental distance which is used to command a change of position parallel to the spindle centre line.

Do not program X , Y or Z in the same block.



X : Dwell

The X word is used with G04 to command a dwell in seconds.

I WORD**a) G40 Active**

For arc programming (G02 or G03) the I value (with sign) is programmed to define the incremental distance parallel with the X axis between the cutter centre and the component arc centre at the start of arc.

b) G41/G42 Active

For arc programming (G02 or G03) the I value (with sign) is programmed to define the incremental distance parallel to the X axis between the start of the arc and the arcentre.

J WORD**a) G40 Active**

For arc programming (G02 and G03) the J value (with sign) is programmed to define the incremental distance parallel with the Y axis between the cutter centre and the component arc centre at the start of arc.

b) G41/G42 Active

For arc programming (G02 and G03) the J value (with sign) is programmed to define the incremental distance parallel to the Y axis between the start of the arc and the arc centre.

K WORD**a) G40 Active**

For arc programming (G02 or G03) the K value (with sign) is programmed to define the incremental distance parallel with the Z axis between the cutter centre and the component arc centre at the start of arc.

b) G41/G42 Active

For arc programming (G02 or G03) the K value (with sign) is programmed to define the incremental distance parallel to the Z axis between the start of the arc and the arc centre.

F WORD

- a) In G95 mode the F word is used to command feed/rev.(optional)
- b) In G94 mode the F word is used to command feed/min.
- c) In G33 mode the F word specifies the lead of the thread. (optional)

P WORD

Used with G10 to define the offset number in the tool geometry file.

Q WORD

Used with G10 the Q word defines the tool location code.

R WORD

a) For circular interpolation (G02 or G03) the arc radius is to the centre of the tool nose radius (G40 active) - or the actual radius required (G41/G42 active).

b) The R word is programmed with G10 to indicate the tool radius in the tool geometry/wear file for use with work surface programming (G41/G42).

S WORD

The four digit S word is used to command the required surface speed in either feet or metres per minute.

T WORD

Tool words are used to cause a tool change, and to activate tool geometry offsets to obtain the desired machining accuracy.

M Word

An M Word is used to initialise auxiliary functions particular to the machine. One M code can be programmed within one program block together with any other part program information.

M CODE LIST FOR DENFORD MILLERS

* ALL M CODES MARKED WITH AN ASTERISK WILL BE EXECUTED AT THE END OF A BLOCK (I. E. AFTER THE AXIS MOVEMENT)

* M00	PROGRAM STOP
* M01	OPTIONAL STOP
* M02	PROGRAM RESET
M03	SPINDLE FORWARD
M04	SPINDLE REVERSE
* M05	SPINDLE STOP
M06	AUTO TOOL CHANGE
M07	COOLANT 'B' ON
M08	COOLANT 'A' ON
* M09	COOLANT OFF
M10	WORK CLAMP OPEN
M11	WORK CLAMP CLOSE
M12	
M13	SPINDLE FORWARD & COOLANT ON
M14	SPINDLE REVERSE & COOLANT ON
M15	PROGRAM INPUT USING, 'MIN P' (SPECIAL FUNCTION)
M16	
M17	
M18	
M19	SPINDLE ORIENTATE

M20 ATC ARM IN
M21 ATC ARM BACK
M22 ATC ARM DOWN
M23 ATC ARM UP
M24 ATC DRAWBAR UNCLAMP
M25 ATC DRAWBAR CLAMP
M26
M27 RESET CAROUSEL TO POCKET ONE
M28 RESET CAROUSEL TO POCKET POSITION
M29 SELECT 'DNC' MODE
M30 PROGRAM RESET & REWIND
M31 INCREMENT PARTS COUNTER
M32
M33
M34
M35
M36
M37 DOOR OPEN TO STOP
M38 DOOR OPEN
M39 DOOR CLOSE
M40 PARTS CATCHER EXTEND
M41 PARTS CATCHER RETRACT
M42

M43	SWARF CONVEYOR FORWARD
M44	SWARF CONVEYOR REVERSE
* M45	SWARF CONVEYOR STOP
M46	
* M47	
M48	LOCK % FEED AND % SPEED AT 100%
M49	CANCEL M48 (DEFAULT)
M50	
M51	
M52	
M53	
M54	
M55	
M56	
M57	
M58	
M59	
M60	
M61	
M62	AUX. 1 ON
M63	AUX. 2 ON
M64	AUX. 1 OFF
M65	AUX. 2 OFF

M66 WAIT FOR INPUT 1
M67 WAIT FOR INPUT 2
M68 ONLY INDEX WITH ALL AXIS AT HOME POSITION
M69 INDEX TURRET ANYWHERE
M70 MIRROR IN X ON
M71 MIRROR IN Y ON
M72
M73 MIRROR IN IV ON
M74
M75
M76 WAIT FOR INPUT 1 TO GO LOW
M77 WAIT FOR INPUT 2 TO GO LOW
M78
M79
M80 MIRROR IN X OFF
M81 MIRROR IN Y OFF
M82
M83 MIRROR IN IV OFF
M84
M85
M86
M87
M88

M89

M90

M91

M92

M93

M94

M95

M96

M97


M98 SUB PROGRAM CALL

M99 SUB PROGRAM END

SECTION 5.3

BASIC MOVEMENTS

- BASIC MOVES



5.3.1 BASIC MOVEMENTS

i) Straight Line Motion (G00, G01) (Descriptions of the appropriate 'G' codes are given in Section 5.2.3).

Almost all motion commands will be programmed as straight line motion for moving to or cutting along a face. During cutting statements, it is only when an arc is to be generated that it will be necessary to change this mode of operation.


Any point on a component can be defined by X,Y & Z dimensions.

In absolute programming the programmer commands the tool to move to a position which is relevant to a component zero. The direction of motion is determined by the system and is dependent on the previous position of the tool.

The programmed word which instructs the control to accept 'X', 'Y' and 'Z' values as absolute is G90.

In incremental programming (G91) the programmer commands the tool point to move to a new position which is a specific distance and direction from its previous position. The direction of motion is determined by the sign of the value for the command.

EXAMPLE 1



This page is intentionally left blank

SECTION 5.4

PROGRAMMING INSTRUCTIONS

- PLANNING AND PROGRAMMING PROCEDURE 5.4.1
- SETTING OF WORKING DATUM 5.4.2
- TOOL LENGTH COMPENSATION 5.4.3
- CUTTER RADIUS COMPENSATION 5.4.4

5.4.1 PLANNING AND PROGRAMMING PROCEDURE

The following procedure may be used as a guide to assist the programmer, by describing each step required in preparing the method of production. Before writing the part program a detailed planning procedure is required.

Planning Procedure

- 1. Receive part drawing. From part drawing information, check suitability of part to be machined against the machine capacity (clearances).
- 2. Determine a method for holding the component.
- 3. Determine the tooling required to suit the method of machining and utilise as much as possible the tools which are permanently in the carousel on the machine.
- 4. Determine the order of machining and the carousel stations.
- 5. Determine planned stops (cycle interrupt procedure incorporating block delete codes) for checking dimensional sizes where required by the operator.
- 6. Determine cutting speeds bearing in mind the following:
 - a) Component material, tooling, rigidity of component.
 - b) The tooling selected: toolholders with carbide inserts, the grade of the carbide insert selected, carbide drills, high speed steel drills, ceramics; for roughing and finishing operations.
- 7. Determine depths of cut and feeds for roughing operations bearing in mind the horsepower/kilowatts available for cutting and the rigidity of the part.
- 8. Determine from surface finish requirements the tooling most suited for the finishing operations and determine feedrates.
- 9. Allocate tool offsets as required.
- 10. Complete planning sheet.

PROGRAMMING PROCEDURE

- 1. After completing the planning sheet draw the component to scale showing the cutter paths (a scale drawing is not mandatory where the component shape and the cutting paths are simple. A sketch may prove sufficient).
- 2. Select a component datum and dimension in scale drawing (or sketch) with the length of cuts relative to the component datum. Carry out necessary calculations at slopes and arcs.
- 3. Draw tooling layout sheet showing tools to be used in the program and indicate the carousel numbers for each tool.
- 4. Complete the tooling layout sheet by indicating the ordering code for each tool and the grade and type of tool to be used.
- 5. Commence writing starting procedure onto program sheets.
- 6. Input instruction codes into machine.

5.4.2 SETTING OF WORKING DATUM

A working datum is essential in all work done on a CNC Milling Machine so that the machine knows the position of the work piece in relation to its own machine datum.

When entering a program the offset values are inputted via the G92 code. The offsets are usually incorporated at the beginning of a program.

e.g

```
N30 G92 X0 Y0 Z0
```


When programming these values are usually set to zero and then determined during setting up.

Note:

If details concerning the dimensions of the workpiece, the precise location of its fixtures and the precise lengths of tools are available the actual axis offset values maybe put in at this stage.

Once the program is in the offset values are usually inputted by the operator driving the reference tool (usually either the longest or the most frequently used) to a known position relative to the workpiece. Comparison of the position readout at machine reference point and at known position relative to the workpiece will reveal the appropriate G92 values, See diagram on next page.

5.4.2 SETTING WORKING DATUM



5.4.2 G92 - TOOLSETTING - TRIAC FANUC

1. **DATUM MACHINE AS IN SECTION 4.6.**
2. **INDEX CAROUSEL TO TOOL NO. 1**
3. **IN JOG OR HANDWHEEL MODE, MOVE TOOL TIP TO COMPONENT ZERO.**
4. **PRESS - POS, TO SELECT POSITION RELATIVE SCREEN**
5. **PRESS X, Y AND Z and CAN, THIS WILL SET ALL THE AXES TO ZERO.**
6. **PRESS - HOME**
7. **PRESS - +Z, +X, -X . THE 3 VALUES FOR THESE AXES ARE ENTERED IN G92 - THIS HAS SET REFERENCE TOOL ie. TOOL NO1, SO OFFSET FOR TOOL1 WILL READ 0 IN THE OFFSET FILE.**
8. **JOG TO POSITION IN Z FOR ALL REMAINING TOOLS AS FOR TOOL No. 1.**
9. **PRESS - OFFSET MENU, AND SELECT OFFSET TO MATCH TOOL NUMBER USING CURSOR**
10. **PRESS - EOB AND WHILST HOLDING THIS KEY PRESS - 6Z KEY, THIS WILL DISPLAY TOOL 2 AND RELATIVE POSITION AT THE BOTTOM OF THE SCREEN**
11. **PRESS - INPUT AND THIS WILL ENTER THE VALUE IN THE OFFSET FILE.**
12. **REPEAT 1. TO 11. FOR REMAINING TOOLS.**
13. **TO ENTER THE TOOL RADIUS COMPENSATION IN THE OFFSET FILE , KEY IN THE VALUES AND PRESS - INPUT OPPOSITE THE RELATIVE OFFSET NUMBER.**

5.4.3 TOOL LENGTH COMPENSATION (OFFSET)

After setting up the G92 command the reference tool will drive the X0 Y0 Z0 (i.e component datum) if given the command:

```
G00 X0 Y0 Z0
```

If a second tool is given the same command it will drive to

```
X0 Y0 Z ?.
```

The value ? is equal to the difference in length between the reference tool and the second tool. This discrepancy can be compensated for by having a tool length offset associated with the second tool. In this case a value of ? would be stored in the tool offset file. The tool offset file may be addressed and modified by the machine operator.

Any movement called for by a tool is modified by the tool offset value currently held on file for that tool, i.e 0 for the reference tool and, if the second tool is shorter than the reference tool, +? for the second tool.

5.4.3 SETTING TOOL LENGTH COMPENSATION ON TRIAC FANUC

The following procedure should be followed to set the tool length compensation for each tool.

- 1) Pick tool to be set.
- 2) In JOG mode move tool tip to component zero.
- 3) Set display to tool offset page.
- 4) Move cursor to an unused offset number.
- 5) Enter Z value using numeric key pad.
- 6) Enter INPUT

This insets the offset value into the address. The value can be called up in the program using the command H.....

Example:

H01

Selects tool offset number one.

5.4.4 CUTTER RADIUS COMPENSATION

Each tool has a cutter radius compensation associated with it. This is of particular value for contouring operations, when the control is capable of modifying the programmed "cutter centre" path to take into account the actual point of cutter contact.

In most cases the "nominal" diameter of the cutter will provide an appropriate level of accuracy. In some cases however, e.g the contouring of a pocket with a tight tolerance on width, the cutter radius offset may have to be adjusted after measuring or probing in a similar fashion to the length offset.

Cutter radius compensations are held in H values and called into the program in the same way as G92 but using the radius compensation commands G41 and G42

e.g N150 G41 G00 X5.0 Y10.0 H05

Note:

G41 calls for compensation on left hand side of work looking along direction of travel.

G42 call for compensation on right hand side of work looking along direction of travel.

This page is intentionally left blank

EXAMPLE PROGRAM FOR TRIAC FANUC

- **TEST PROGRAM FOR TRIAC FANUC**

:0100

N10 G21 G40 G49 G80

N20 G91 G94 G00 G28 X0 Y0 Z0

- **THE FIRST TWO LINES SET THE MACHINE UP IN THE UNITS AND FORMAT REQUIRED. MACHINE SENT TO REF. POSITION.**

N30 M06 T0101

- **TOOL 1 IS INSERTED INTO THE SPINDLE (6MM SLOT DRILL)**

N40 G92 X Y Z

- **DATUM POSITION - X, Y AND Z VALUES TAKEN FROM THE MACHINE POSITION READ-OUT.**

N50 G90 G00 X0 Y20 Z10 G43 H01 M03 S3000

N60 G01 Z-2 F120

N70 Y50

N80 X35

N90 Y65

N100 X55 Y70

N110 X70

N120 Y50

N130 X105

N140 Y20

N150 X70

N160 Y0

N170 X0

N180 Y22


N190 G00 Z10

N200 M05

N210 G91 G28 X0 Y0 Z0

N220 M30

EXAMPLE 2



TEST PROGRAM FOR TRIAC FANUC

:0200

N10 G21 G40 G49 G80

N20 G91 G94 G00 G28 X0 Y0 Z0

- **THE FIRST TWO LINES SET THE MACHINE UP IN THE UNITS AND FORMAT REQUIRED. MACHINE SENT TO REF. POSITION.**

N30 M06 T0101

- **TOOL 1 IS INSERTED INTO THE SPINDLE.**

N40 G92 X Y Z

- **DATUM POSITION - X, Y AND Z VALUES TAKEN FROM THE "MACHINE" READ-OUT.**

N50 G90 G41 G00 X0 Y-10 Z10 G43 H01

- **CUTTER COMPENSATION USED H17= OFFSET No.17**

N60 M03 S3000

N80 Z-2 F120

N85 G00 Y0 X0 G14 H17 (OFFSET 17 IS RADIUS OF TOOL 1.).

N86 G01 Y20

N90 Y80 F150

N100 G02 X10 Y90 R10

N110 G01 X45

N120 X60 Y70

N130 X80

N140 G02 X90 Y60 R10

N150 G01 Y50

N160 G03 X100 Y40 R10

N170 G01 X105

N180 Y10

N190 G02 X95 Y0 I-10 J0

N200 G01 X10

N210 G02 X0 Y10 I0 J10

N220 G01 Y22

N230 G00 Z2 G40

N240 Y40 G42 H17

N250 X40

N260 G01 Z-2


N270 G02 X40 Y40 I0 J-10

N280 G01 Z10 G40

N290 M05

N300 G91 G00 G28 X0 Y0 Z0

EXAMPLE 3



:3000

N10 G21 G40 G49 H00 G80

N20 G91 G94 G00 G28 X0 Y0 Z0

N30 G92 XYZ (**DATUM POSITION**)

(**No. 4 CENTRE DRILL**)

N40 M06 T0101

N50 M03 S2000

N60 G90 G43 H01 G00 X0 Y20 Z10

N70 G81 G99 X0 Y20 Z-7 R2 F80

N80 G99 X17.32 Y10

N90 G99 Y-10

N100 G99 X0 Y-20

N110 G99 X-17.32 Y-10

N120 G98 Y10

N130 G80 M05

N140 G91 G28 X0 Y0 Z0

(**5mm TWIST DRILL**)

N150 G49 M06 T02 H00

N160 M03 S3000

N170 G90 G43 H02 G00 X0 Y20 Z10

N180 G83 G99 X0 Y20 Z-12 R2 Q7 F100

N190 G99 X17.32 Y10

N200 G99 Y-10

N210 G99 X0 Y-20

N220 G99 X-17.32 Y-10

N230 G98 Y10

N240 G80 M05

N250 G91 G28 X0 Y0 Z0

(M6 x 1 TAP)

N260 G49 M06 T03 H00

N270 M03 S200

N280 G90 G43 H03 G00 X0 Y20 Z10

N290 G84 G99 X0 Y20 Z-8 R5 F200

N300 G99 X17.32 Y10

N310 G99 X0 Y-20

N320 G99 X-17.32 Y-10

N330 G98 Y10

N340 G80 M05

N350 G91 G28 X0 Y0 Z0

(6mm SLOT DRILL)

N360 G49 M06 T04 H00

N370 M03 S2600

N380 G90 G43 H04 G00 X-30 Y10 Z10

N390 Z2

(THREE AXES LINEAR MOVE)

N400 G01 Z0 F180

N410 X0 Y40 Z-2

N420 X30 Y10 Z0

N430 G00 Z2

N440 X-30 Y-30

(PLANE SWITCHING)

N450 G18 G01 Z0

N460 G02 X30 Z0 R300

N470 G17 G00 Z10

N480 M05

N490 G91 G28 X0 Y0 Z0

N500 M30

This page is intentionally left blank

SECTION 5.5

SUBROUTINES AND EXAMPLES OF CYCLES

- SUBROUTINES 5.5.1
- G73 HIGH SPEED PECK DRILLING 5.5.2
- G74 LEFT HAND TAPPING 5.5.3
- G76 FINE BORING CYCLE 5.5.4
- G81/G82 DRILLING CYCLE, SPOT BORING CYCLE 5.5.5
- G83 PECK DRILLING CYCLE 5.5.6
- G84/G85 TAPPING CYCLE 5.5.7
- G87 BORING CYCLE, BACK BORING CYCLE 5.5.8

PROGRAM AND SUBROUTINE IDENTIFICATION

The first block of a program/subroutine must contain an identification number.

The program would be as follows:-

```
%                               Wind/Rewind Stop
:1234                           Program Number
N10
.... )
..... )                         Part Program Blocks )
..... )
N ..... M30                     Last Block
%                               Wind/Rewind Stop
```

The Subroutine would be as follows:-

```
%
:5678                           Subroutine Number
N10 .....
.....
.....
N..... M99                       Jump Back to Main Program.
```



5.5.1 SUBPROGRAMS (SUBROUTINES)

Using the program jump functions, a machining program with repeated machining or function sequences can be simplified.


The machining sequences, which are repeated and can be used several times, are stored as subroutines and called up using the program jump functions.

M98 - Jump command to another program.

M99 - Return command.




M99 can be used to return to the start of the program.



M99 generally indicates the end of a subroutine and allows the jump back to the main program. If it is used with 'P' address this indicates the 'Jump To' block number. The program will read the M99 P10 (GOTO N10), i.e. automatic return to the start.

Line N10 must read M00 to stop the cycle to enable a component to be loaded. All information prior to N10 (i.e. standard tool geometry/wear) would not be read after the first cycle. M30 would not be programmed in this case.

5.5.2 G73 HIGH SPEED PECK DRILLING



Used for efficient machining, permits very low retraction value.

N100 M06 T03

N110 M03 S2000

N120 G90 G00 X10 Y10 Z10 P43 H03


N130 G73 G99 X10 Y10 Z-20 Q3 R2 F2000

N140 X20

N150 X30

N160 G80

5.5.3 G74 LEFT HAND TAPPING



N100 M06 T04



N110 M03 S2000

N120 G90 G00 X00 Y20 Z10

N130 G91 G74 G99 X20 Z-12 R-8 K3 F100

N140 G80

5.5.4 G76 FINE BORING CYCLE



N100 M06 T05


N110 M03 S2000

N120 G90 G00 X00 Y20 Z10

N130 G91 G76 G99 X20 Z-12 Q0.5 R-8 K3 F200

N140 G80

5.5.5 G81/G82 DRILLING CYCLE, SPOT BORING CYCLE



N100 M06 T05

N110 M03 S2000

N120 G90 G00 X30 Y20 Z10

N130 G81 G99 X30 Y20 Z-10 R2 F200

N140 X40



N150 G98 X60

N160 G80

Note:

G82 is the same as G81 but has a dwell time at the bottom of the hole.

5.5.6 G83 PECK DRILLING CYCLE



N100 M06 T03

N110 M03 S2000

N120 G90 G00 X10 Y10 Z10


N130 G83 G99 X10 Y10 Z-20 Q3 R2 F200

N140 X20

N150 G98 X30

N160 G80

5.5.7 G84/G85 TAPPING CYCLE



N100 M06 T03

N110 M03 S250

N120 G90 G00 X10 Y10 Z10

N130 G84 G99 X10 Y10 Z-20 R5 F250

N140 X20

N150 G98 X30

N160 G80


Note:

Spindle direction is reversed at the bottom of the hole for G84, but for G85 the spindle direction is constant.

5.5.8 G87 BORING CYCLE, BACK BORING CYCLE

NOTE:

MOUNT WORK CLEAR OF TABLE.



N100 M06 T04

N110 M03 S2000

N120 G00 X20 Y10 Z20

N130 G87 G98 X20 Y10 Z20 Q4 R-27 F100

N140 X40

N150 X60

N160 G80

Note:

After tool is in position spindle stops. The spindle then shifts in direction opposite to the tool and the tool is placed at the bottom of the hole. The spindle rotates clockwise and machining is performed upwards.

SECTION 6

CUSTOMER'S OBSERVATIONS OF THIS MANUAL

- **PROFORMA FOR RETURN TO DENFORDS**

6.1

This page is intentionally blank.

**PLEASE RETURN TO DENFORDS IF YOU FEEL ANY
AMENDMENTS ARE REQUIRED TO THIS MANUAL.**

FROM:

TO:

THE TECHNICAL AUTHOR,
DENFORD MACHINE TOOLS LIMITED,
BIRDS ROYD,
BRIGHOUSE,
WEST YORKSHIRE.
HD6 1NB

TEL.: 0484 712264
TELEX : 517478
FAX.: 0484 722160

ALL AMENDMENTS WILL BE CHECKED AT DENFORDS THEN
INCORPORATED INTO THE NEXT REPRINT OF THE TRIAC FANUC
INSTRUCTION MANUAL.

PART OF MANUAL REQUIRING AMENDMENT:

SECTION:.....PAGE:.....PARA:.....FIG:.....

AMENDMENT TO BE MADE / ANY OTHER COMMENT:

.....**SIGNATURE**.....**POSITION IN COMPANY.**

This page is intentionally blank.

APPENDIX

This page is intentionally blank.

APPENDIX 1 GLOSSARY OF TERMS

ARC

A portion of a circle

ARC CENTRE OFFSET

The incremental distance between the programs cutter path and the arc centre in the axes directions. The X,Y and Z values are written as the I,J and K amounts without a directional sign.

ASCII

American Standard for Information Interchange.

AUTOMATIC CYCLE

Is a mode of control operation that continuously runs the tape or stored program until a program stop or end of program word is read.

AUXILIARY FUNCTION

The function of a machine other than the co-ordinate commands. F00, S100, T0100, M08.

AXIS

X axis: Line perpendicular to the spindle centre line (absolute)

U axis: Line perpendicular to the spindle centre line (incremental)

Z axis: Line parallel with the spindle centre line (absolute).

W axis: Line parallel with the spindle centre line (incremental).

Y axis: Line perpendicular to both the X and Z axes (absolute).

V axis: Line perpendicular to both the U and W axes (incremental).

BINARY

A system for describing numbers using only two digits.

BINARY CODED DECIMAL

A system of represented numbers comprised of a combination of four binary bits running across the tape; letters are also described in this way.

BIT

The smallest programmable unit (i.e 1 or 0) in machine code.

8 Bits = 1 Byte

BLOCK

A word or words that collectively provide sufficient information for a complete operation. The block is separated from other blocks by an end of block character.

this page is intentionally left blank

BLOCK DELETE

Is a feature which provides means for skipping blocks (which have been preceded by a slash/code) at the discretion of the operator.

BUFFER STORAGE

Is an information storing area which is utilised to transfer the stored data to active storage almost instantaneously.

CANNED CYCLE

Is an automatic motion cycle which is held in buffer storage for the duration of the amount of cycle repeats programmed.

CHARACTER

A number, letter or symbol as punched across the tape and constituting part of the row.

CIRCULAR INTERPOLATION

A means of programming an arc by providing a few basic statements.

CLOSED LOOP

A system in which the result of the output is measured and fed back for comparison with the input.

CNC

Computer numerical control See SOFTWARED N.C

COMMAND

A signal or group of signals initiating one step in the execution of a program.

CONTOURING (CONTINUOUS PATH)

Co-ordinated simultaneous motion of two or more axes.

CORNERING

The effect at the machine due to the difference of electrical commands and slide positioning whilst commanding an abrupt change of direction.

C.S.S.

Constant Surface Speed. A feature in a control system which tracks the point of a cutting tool so that the spindle can be constantly monitored to give the correct peripheral speed condition.

C.P.U.

Central Processing Unit.

DECODE

The translation from tape coded language to control recognisable language.

DRY RUN

The use of this function enables the operator to run through the program replacing the programmed feed rates with the maximum jog feed, to test run the program and check tool clearance.

DWELL

A programmed time delay.

EDIT

Having put the program into memory (via the tape reader), the machine can then be operated from memory and suspect block of data can then be displayed for examination.

The faulty block can then be erased or correct information put in its place by means of MDI. The batch can then be run off entirely from the memory.

The addition of a tape punch enables correct tape to be produced automatically from edited and stored data.

EIA

Electrical Industries association has been responsible for setting many N.C. standards, one being tape coding information.

ENCODE

The translation from control recognisable language to tape coded language.

ENCODER

Device for comparing the position with the control input instruction.

END OF BLOCK

A character punched on a N.C. tape which denotes the end of a block of data.

EXECUTIVE

In CNC systems the executive software determines the manner in which the program data is processed.

FEED HOLD

At any stage in the cycle, the operator can stop the machine movements using the cycle stop key.

FEEDRATE

Is commanded in the N.C program by the F word and used by the control to drive the axes. The rate of feed may be programmed as FEED/MIN or FEED/REV.

FEEDRATE

Is an interrupt used to hold axes motion

FEEDRATE OVERRIDE

A manual function can be used by the operator to override the programmed feed rate within certain limits.

FOLLOWING ERROR

The lag distance between the actual machine position and the command position.

FORMAT

The arrangement and overall pattern in which the input data is organised (formatted).

G CODE

A preparatory code in the program which determines the control mode.

HARDWARE

The physical components of a control system or computer.

HARDWIRED

A numerical control system which is dedicated to driving a machine through committed circuit connections, and requiring the input data to be in a fixed format.

I REGISTER

A value which when programmed is used by the control as an X axis arc centre offset.

INCREMENTAL PROGRAMMING

A method of programming in which the motion statements relate from the previous programmed position. The signs which accompany the departure commands in this system are directional in meaning.

INPUT

The transfer of external information into the control system.

INTERGRATED CIRCUIT

A complete circuit constructed within or on the surface of a silicon chip.

INTERFACE

The medium through which the control or computer directs the machine tool.

INTERPOLATION

The method used by the control system to achieve a series of approximations via. straight lines to enable an acceptable execution for tapers or arcs.

ISO

International Standards Organisation.

K REGISTER

A value which when programmed is used by the control as a Z axis arc centre offset or as a velocity rate for feed and threading.

LEADER

A portion of tape which precedes and follows the coded section to allow for handling or loading onto reels.

LOOP

A tape which is spliced together and not loaded to the reels.

M CODE (Miscellaneous Function)

The M words are used by the machine tool builder to indicate certain auxiliary functions such as coolant on, turret index, speed range etc.

MANUAL DATA INPUT (MDI)

A means of inserting data into the control system manually. The data entered is identical to that entered from a control tape or stored program.

MANUSCRIPT

A form used by the programmer for listing the detailed instructions which constitute a part program. These can be transcribed directly by the tape preparation device.

MEMORY

The storage capacity of a system to retain a part program or Programs.

MODAL

Information that is entered into the control and retained until changed.

N WORD

A word comprising a unique sequence number which is used to identify a complete block of information.

OCTAL NUMBERS

A numbering system which operates to a base of 8. Octal is more readily convertible to the decimal system than is the binary system.

OPEN LOOP

A system in which the output cannot be measured and feedback for comparison with the input.

OPTIONAL STOP

A miscellaneous command which is given by the programmer to stop the spindle and feed at a specific point in the program at the discretion of the operator.

PARITY CHECK

An automatic method of checking tape rows to establish that an odd or even parity system has been consistently punched. Should this check fail, the reader will stop to indicate an error in the preparation equipment or the reader itself.

PROGRAM STOP

A miscellaneous command which is given by the programmer to stop the spindle and feed at a specific point in the program.

RESOLVER

A device for comparing the position with the control input instruction.

RECTANGULAR CO-ORDINATES

A component graphically shown as three perpendicular axes (X,Y and Z) along which any point can be described in terms of distance and direction from any other point. The part program is written from this source.

RESOLUTION

The smallest increment of distance that will be developed by the control system in order to command machine motion.

ROW

A row of holes perpendicular to the tape edge which contain the character.

S ADDRESS

A word used in commanding the spindle speed.

SEQUENCE NUMBER

See N Word.

SOFTWIRED N.C.

A control system that has been pre-programmed with software to enable it to drive a machine tool.

SUB-ROUTINE

A stored sub program which is called from the main program.

STEP-BY-STEP OPERATION

An extension of MDI permits the machine to operate block-by-block, to permit the checking of each stage of the job, if required.

TAB

Tab characters may be used to space out the words in a program manuscript in columns if required.

TOOL OFFSET

A feature that allows the operator to make tool adjustments to compensate for the difference between the actual and the programmed setting dimensions.

TRACK

A path of holes parallel with the tape along which information may be stored by the presence or absence of holes.

U WORD

The U Word is used to command motion perpendicular to the spindle centre line (incremental).

W WORD

The W Word is used to command motion parallel to the spindle centre line (incremental).

V WORD

The V Word is used to command motion perpendicular to both U and W axes.

WORD

A combination of the letter address and digits.

ADDRESS	DIGITS	WORD
X	+002.0000	X+002.0000
F	1.9990	F1.9990

X WORD

On 2 and 4 axis machines X Word is used to command motion perpendicular to the spindle centre line (absolute).

Z WORD

On 2 and 4 axis machines Z Word is used to command motion parallel to the spindle centre line (absolute).

Y WORD

On 2 and 4 axis machines Y Word is used to command motion perpendicular to both X and Z (absolute)

ZERO

In absolute programming, zero is the point from which all other dimensions are referenced.

APPENDIX 2 LIST OF ABBREVIATIONS

G.B.T. NO.	= Group Block Terminal
EXECUTE OR MDI	= Manual Data Input
MSD	= Machine Set Up Data (or Parameters)
RAM	= Random Access Memory
ROM	= Read Only Memory
PROM	= Programmable Read Only Memory
EPROM	= Erasable Programmable Read Only Memory
PCI	= Program Controlled Interface (i.e. Ladder Diagram in Software).
PWM	= Pulse Width Modulated G.E Servo Drive or Hi-Ak Drives.
SCR	= Silicon Controlled Rectifier (i.e Thyristor Drives used on Spindle)
TRIAC	= Solid State Relay
I.P.	= Initial Position or Zero Ref. Point
BCD	= Binary Coded Decimal
LED	= Light Emitting Diodes
IC	= Input Conditioner or Input Filter
OD	= Output Driver
+VE	= Positive
-VE	= Negative

DVM	= Digital Voltmeter
POT	= Potentiometer or Variable Resistor
LSI	= Large Scale Integration
PCL	= Programmable Controller Language
MCL	= Machine Control Logic

This page is intentionally blank.

APPENDIX 3

TRIGONOMETRY AND GEOMETRY

- TRIGONOMETRY
- GEOMETRY

TRIGONOMETRY WITH EXAMPLES


a) Tangent

In Fig. 2 AOB is an angle of say 30 Degrees. The triangles LPO, MQO, NRO are similar because they all share the common angle of 30 Degrees. Therefore a common ratio for the three triangles can be shown as:

$$\frac{LP}{OP} = \frac{MQ}{OQ} = \frac{NR}{OR} \quad \text{Fig. 2}$$

If these sides were known, then dividing LP by OP and MQ by OQ and so on will produce the same common ratio.

If side LP is 5 mm and OP is 8.66 mm then LP/OP produces a ratio of 0.5774 or tangent value for 30 Degrees, a set of tangent tables are compiled in this way.



In the triangle LOP, side LP is opposite to the angle AOB, side OP is adjacent to the angle LOP, so to calculate a tangent ratio for the triangle LOP may be shown as:

$$\text{Tangent value} = \frac{\text{Opposite Side}}{\text{Adjacent side}}$$

b) Sine

In Fig. 2 the triangles LPO, MQO, NRO are similar because they all share the same angle (90 Degrees) at P, Q and R. Therefore a common ratio for three triangles can be shown as:

$$\frac{PL}{OL} = \frac{QM}{OM} = \frac{RN}{ON}$$

Therefore the ratio of PL/OL depends on the angle value of AOB only and dividing these two values will always produce the same common ratio.

If side PL is 5 mm and OL is 10 mm then PL/OL produces a ratio of .5000 or sine value for 30 Degrees, a set of sine tables are compiled in this way. In the triangle LOP, side PL is opposite to the angle AOB, side OL is the hypotenuse of the triangle LOP, so to calculate a sine ratio for the triangle LOP may be shown as:

$$\text{Sine Value} = \frac{\text{Opposite Side}}{\text{Hypotenuse}}$$

C) Cosine

It is also true that in Fig. 2 the ratios:

$$\frac{OP}{OL} = \frac{OQ}{OM} = \frac{OR}{ON}$$

Therefore the ratio of OP/OL depends on the angle value of AOB only and dividing these two values will always produce the same common ratio.

If side OP is 8.66 mm and OL is 10 mm then OP/OL produces a ratio of .866 or cosine value for 30 Degrees, a set of cosine tables are compiled in this way. In the triangle LOP, side OP is adjacent to the angle AOB, side OL is the hypotenuse of the triangle LOP, so to calculate a cosine ratio for the triangle LOP may be shown as:

$$\text{Cosine Value} = \frac{\text{Adjacent Side}}{\text{Hypotenuse}}$$

SUMMARY

Tangent

$$\text{TAN} = \text{Opp. Side/Adj. Side}$$

$$\text{also Opp. Side} = \text{Tan} \times \text{Adj. Side}$$

$$\text{Adj. Side} = \text{Opp. Side/Tan}$$

Sine

$$\text{SIN} = \text{Opp. Side/Hypot.}$$

$$\text{also Opp. Side} = \text{Sin} \times \text{Hypot.}$$

$$\text{Hypot.} = \text{Opp. Side/Sin}$$

Cosine


$$\text{COS} = \text{Adj. Side/Hypot.}$$

$$\text{also Adj. Side} = \text{Cos} \times \text{Hypot.}$$

$$\text{Hypot.} = \text{Adj. Side/Cos}$$

EXAMPLES:

Determine X values



1) Solution

Find adjacent side knowing opposite.

$$\text{Adj} = \frac{\text{Opp}}{\text{Tan } 35 \text{ Degrees}}$$

$$A = \frac{7}{0.7002}$$

$$A = 9.9971 = X$$

2) Solution

$$O = \text{Sin } 35 \text{ Degree} \times \text{Hypot}$$

$$O = .5736 \times 10$$

$$O = 5.7360 = X$$

3) Solution


Find angle knowing adjacent side and hypotenuse.

$$\text{Cos} = \frac{\text{Adj.}}{\text{Hypot.}}$$

$$\text{Cos} = \frac{2.9365}{7} = 0.4195 \text{ (as cosine ratio)}$$

$$0.4195 \text{ from cosine tables} = 65 \text{ deg } 12' = X$$

4/




4) Solution

Find X distance on component chamfer

$$X = \tan 30 \times 5$$

$$X = 2.887 \text{ mm}$$

5/



5) Solution

Determine Z distance on thread relief.


$$Z = \frac{2.250}{\tan 28}$$

$$Z = 4.232 \text{ mm}$$

GEOMETRY

DEFINITION Right Angle

If a straight line OP meets another straight line AOB as shown in Fig. 1, so as to make the adjacent angles POA, POB equal, each angle is called a right angle.



Acute Angle.


An acute angle is an angle less than a right angle.

Obtuse Angle.


An obtuse angle is an angle greater than a right angle but less than two right angles.

Reflex Angle.

A reflex angle is an angle between two and four right angles. Any two angles whose sum is two right angles are called supplementary. Two angles whose sum is one right angle are called complementary.



If two straight lines intersect, the vertically opposite angles are equal. In fig. 2, where two lines intersect, a is equal to b and x is equal to y.



If two straight lines in the same plane do not meet they are called parallel lines. In fig. 3 the line is called a transversal line, angles a and d are called alternative angles; angles c and d are called corresponding angles; angles b and d are called interior angles.

Therefore if a transversal line PQ cuts two parallel lines, angles a and d are equal, angles c and d are equal.

Angle properties of the circle.

Circle 1




fig 4

In figure 4, line DE is tangent to circle 1, because it only touches the circle at one point, line AB is a chord of circle 1, if OC is perpendicular to the chord AB from the centre of circle 1 then AC is equal to CB.

Circle 2




fig 5

The angle in a semi circle is a right angle. In fig 5 line AB passes through the centre of circle 2 at O. Any point chosen within the semi circle at C will produce a right angle ACB.


APPENDIX 4

TABLES OF INFORMATION

- **USEFUL FORMULAE**


This page is intentionally blank.

5.8.1 USEFUL FORMULAE FOR DETERMINING CONTOUR CHANGE POINTS




$$\Delta x = r \cdot \frac{\cos \frac{\alpha_2 + \alpha_1}{2}}{\cos \frac{\alpha_2 - \alpha_1}{2}}$$

$$\Delta z = r \cdot \frac{\sin \frac{\alpha_2 + \alpha_1}{2}}{\cos \frac{\alpha_2 - \alpha_1}{2}}$$




$$\Delta x = r$$

$$\Delta z = r \cdot \tan \frac{\alpha}{2}$$



$$\Delta x = r \cdot \tan \left(45 - \frac{\alpha}{2} \right)$$

$$\Delta z = r$$




$$\Delta w = R \cos \alpha$$

$$\Delta x = r \cos \alpha$$


$$\Delta y = R \sin \alpha$$

$$\Delta z = r \sin \alpha$$



$$\Delta x = r$$

$$\Delta z = \sqrt{[(R+r)^2 - (\Delta w+r)^2] - \Delta y}$$





$$\Delta x = r$$

$$\Delta z = \Delta y - \sqrt{[(R-r)^2 - (\Delta w-r)^2]}$$


$$\Delta y = r$$

$$\Delta x = \sqrt{[(R+r)^2 - (\Delta y + r)^2]} - \Delta w$$



$$\Delta z = r$$

$$\Delta x = \Delta w - \sqrt{[(R-r)^2 - (\Delta y - r)^2]}$$



$$\Delta w = R \cos \alpha$$

$$\Delta x = r \cos \alpha$$

$$\Delta y = R \sin \alpha$$


$$\Delta z = r \sin \alpha$$


$$\Delta y = R \sin (90 - \alpha - \beta)$$

$$\Delta w = R \sin (\alpha - \beta)$$

$$\tan \alpha = \frac{\Delta z}{\Delta x}$$

$$\sin \beta = \frac{\Delta z}{2R \sin \alpha}$$






$$\Delta w = R \cos \alpha$$

$$\Delta x = r \cos \alpha$$

$$\Delta y = R \sin \alpha$$

$$\Delta z = r \sin \alpha$$



$$x_m = R \frac{\sin (\alpha + \theta_1)}{\cos \alpha}$$

$$z_m = R \frac{\cos (\alpha + \theta_1)}{\cos \alpha}$$


$$\alpha = \frac{90 - \theta_1 - \theta_2}{2}$$

$$w_1 = R \sin \theta_1$$

$$w_2 = R \cos \theta_2$$

$$y_1 = R \cos \theta_1$$

$$y_2 = R \sin \theta_2$$



$$x_m = R \frac{\sin (\alpha + \theta_1)}{\cos \alpha}$$

$$z_m = R \frac{\cos (\alpha + \theta_1)}{\cos \alpha}$$


$$\alpha = \frac{90 - \theta_1 - \theta_2}{2}$$

$$w_1 = (R + r) \sin \theta_1$$

$$w_2 = (R + r) \cos \theta_2$$

$$y_1 = (R + r) \cos \theta_1$$

$$y_2 = (R + r) \sin \theta_2$$



$$x_m = R \frac{\cos (\alpha + \theta_1)}{\cos \alpha}$$

$$z_m = R \frac{\sin (\alpha + \theta_1)}{\cos \alpha}$$


$$\alpha = \frac{90 - \theta_1 - \theta_2}{2}$$

$$w_1 = R \cos \theta_1$$

$$w_2 = R \sin \theta_2$$

$$y_1 = R \sin \theta_1$$

$$y_2 = R \cos \theta_2$$



$$x_m = R \frac{\cos (\alpha + \theta_1)}{\cos \alpha}$$

$$z_m = R \frac{\sin (\alpha + \theta_1)}{\cos \alpha}$$


$$\alpha = \frac{90 - \theta_1 - \theta_2}{2}$$

$$w_1 = (R - r) \cos \theta_1$$

$$w_2 = (R - r) \sin \theta_2$$

$$y_1 = (R - r) \sin \theta_1$$

$$y_2 = (R - r) \cos \theta_2$$



$$\Delta z_1 = \sin \gamma (R_1 - r)$$

$$\Delta x_1 = R_1 - \cos \gamma (R_1 - r)$$

$$\Delta z_2 = \sin \gamma (R_2 + r)$$

$$\Delta x_2 = R_2 - \cos \gamma (R_2 + r)$$

$$\tan \beta = \frac{R_1 + R_2 - \frac{D_2 - D_1}{2}}{A}$$

$$\gamma = \alpha - \beta$$

$$\sin \alpha = \frac{R_1 + R_2}{\sqrt{[A^2 + (R_1 + R_2 - \frac{D_2 - D_1}{2})^2]}}$$

INDEX

This page is left intentionally blank

INDEX

A

Abbreviations	132
Access points	33
Air conditioning unit	35
Automatic operation panel	47
Axis definitions	73

B

Basic movements	84
---------------------------	----

C

Capacity diagrams	12
Cutter radius compensation	95

D

Datum of axes	56
-------------------------	----

E

Electrical connection	31
EMERGENCY STOP	51
Extent diagrams	11

F

FANUC Data input panel	42,43
FANUC Display screen	42
FANUC Operators panel	45

G

G CODES	69
G73 High speed peck drilling	110
G74 Left hand tapping	111
G76 Fine boring	112,
G81/G82 Drilling, Spot boring	113
G83 Peck drilling	114
G84/G85 Tapping	115
G87 Boring, Back boring	116
Geometry	141
Glossary of terms	123

I

Installation	25
Inventory	7

L

Levelling procedure	29
Lifting a Triac Fanuc	28

M

M CODES	78
Machine preparation	36
Machine Specification	15
Manual feed override	51
Manual operation panel	49
Manual Programming	61

N

N.C. Controller Specification	17
---	----

O

Operation	37
Operators panel	52
Optional extras	22

P

Part programming words	66
Planning a program	88
Program protection unit	46
Programming instructions	87
Programming procedure	89

R

Run in procedure	57
----------------------------	----

S

Safety devices	41
Safety precautions	39
Section 1	7
Section 2	9
Section 3	25
Section 4	37
Section 5	59,
Section 6	117
Section Index	4
Specification	9
Start up procedure	55
Subroutines	109

T

Tape format	67
Tool changing, A.T.C.	54
Tool changing, Manual	53
Tool changing, Pneumatic	54
Tool length compensation	93
Trigonometry	136

W

Word descriptions	65
Word details	68
Working datum	90