Site Preparation Guide





Copyright

Copyright © 2018 Stratasys Ltd. All rights reserved.

This documentation contains proprietary information of Stratasys Ltd. This information is supplied solely to assist authorized users of this Stratasys 3D printing system. No part of this document may be used for other purposes, and it may not be disclosed to other parties.

The specifications on which this document is based are subject to change without notice.

No part of this book may be reproduced in any form or by any means, nor stored in a database or retrieval system, without prior permission in writing from Stratasys Ltd.

If this document is distributed as a PDF file, you may print it for internal use.

April 2018

DOC-34011 Rev. I

Trademarks

The following are registered trademarks of Stratasys Ltd.: Stratasys[®], Objet[®], FullCure[®].

All names of products and services cited in this book are trademarks or registered trademarks of their respective companies.

Feedback

If you have any questions or comments about the way information is presented in this document, or if you have any suggestions for future editions, please send a message to c-support@stratasys.com.

Contents

Introduction	5
About this Guide	
Physical Description	6
Size and Weight	6
Shipment and Delivery	7
Shipping Information and Customer Responsibility Shipping Pallet Lifting Equipment Unloading	
Installation Area	8
Floor Plan (Printer Area)	9
Workstation Requirements	10
Electrical Requirements	11
Power Grounding Circuit Breaker Residual Current Device (RCD) Power Connection UPS (Uninterrupted Power Supply)	
Communication Lines	14
Local Area Network Telephone	
Environmental Conditions	15
Temperature and Humidity Air Quality Noise Level	15
Accessories and Utilities	16
Start-Up Kit Fire Safety Equipment	
Materials Handling and Storage	17
Printing Materials Cleaning Solvent	

Site Preparation Checklist	. 1	8	3	
----------------------------	-----	---	---	--

DOC-34011 Rev. I 4

Desktop Introduction

Introduction

About this Guide

The information and requirements provided in this document ensure proper installation and operation of the Desktop 3D printing system. The customer is responsible for preparing the site as described in this document, and according to any applicable local regulations.

If you have any questions about the information in this document, contact your Stratasys representative.

All site requirements must be met before the installation date. The Site Preparation Checklist should be submitted to your Stratasys representative. Shipping will be arranged after the checklist is received by Stratasys.

Non-compliance with requirements specified in this document may result in additional installation charges.

Installation and Training Schedule

Installation and training take two work days, and include:

- Basic installation and adjustment
- Operator training including practice under supervision



Physical Description

The Desktop 3D printing system consists of the following main components:

- printer
- printer computer (built into the printer)
- printer-server workstation (provided by the customer)

Figure 1 Objet Desktop 3D printer



Size and Weight

The following table shows the size and weight of the printer.

Table 1 Size and weight

W × H × D (cm)	W × H × D (inch)	Weight (kg/lb)
82.6 × 60 × 62	32.5 × 23.6 × 24.4	106 kg / 234 lb



- W = Width; H = Height; D= Depth
- The weight of the printer does not include printing materials.

Shipment and Delivery

Shipping Information and Customer Responsibility

Shipment to the customer will be arranged by Stratasys as indicated in the "ship to" part of the invoice. The customer is responsible for providing detailed delivery information, including, whether or not there is loading dock at the delivery site.

The customer is responsible for transporting the printer to a suitable installation site. Upon request, your Stratasys service provider will advise regarding these matters.



Note:

Only Stratasys-certified Customer Support Engineers are authorized to unpack and install equipment supplied.

Shipping Pallet

The following table shows the approximate size and weight of the printing system mounted on a pallet.

Table 2 Size and weight of printer on shipping pallet

W × H × D (cm)	W × H × D (inch)	Weight (kg/lb)
114 × 86 × 77.5	44.9 × 33.9 × 30.5	141 kg / 311 lb



W = Width; H = Height; D = Depth

Lifting Equipment

lifting capacity: 150 kg (330 lb)

• extension: 100 cm (40 in.)

Unloading

The unloading area should be a level surface.

The installation location must be accessible from the unloading area. The customer is responsible for unloading the printer from the truck and transferring it to the installation location.



Desktop Installation Area

Installation Area

The installation area should be free of sources of vibration and electromagnetic interference that could affect the proper functioning of the printer.

The printer should be positioned on a stable surface, such as a stand with lockable wheels.

A suitable stand can be ordered from Stratasys.

The floor gradient should be less than 0.5% (5 mm per meter).

The maximum table load is 150 kg (330 lb).

The required table height is 62-72 cm (24.8-28.8 in.).

The server workstation and the printer should be located in the same room.

The cable between the server workstation and the printer should not exceed 5 meters (16 feet). The communication cable provided should not be extended or replaced with a longer cable.

Clearance around and above the printer should ensure convenient access and servicing.

The area around the printer should remain dry at all times. Do not place the cleaning station within 5 meters (16 feet) of the printer.

Shelves and cabinets are recommended near the printer for convenient storage of tools, parts, accessories, manuals, and materials.




Desktop Installation Area

Floor Plan (Printer Area)

The following is a sample floor plan, showing the 3D printing system—the printer and the workstation. The dimensions shown in the figure are the minimum clearance requirements.

Figure 2 Printer floor plan (sample, not to scale)





Workstation Requirements

The customer is responsible for supplying a computer with the following specifications for the server workstation.

	Requirement	
Computer Type	Standard desktop PC ¹	
Processor	Intel [®] Core™ i5 or higher	
Operating System	Windows [®] 7 64-bit, Windows [®] 8.1 64-bit, or Windows [®] 10 64-bit ² Use a professional edition of Windows [®] only.	
RAM	8 GB or more ²	
	Open GL®	
Graphics Card ³	Memory: 1 GB or more; 2 GB recommended for dental applications	
	For server workstation: VGA connector ⁴	
Optical Drive	CD/DVD ROM	
HDD/SSD	80 GB or more (minimum free space on disk: 40 GB)	
Network Card	LAN TCP/IP (2 network cards for server workstation; 1 network card for each client workstation)	
Mouse/Keyboard Connection	USB	
Monitor Cable	One cable with VGA connector	
Anti-virus	Recommended: TrendMicro, Eset NOD32, AVG, Kaspersky ⁵	

Administrator privileges are required on the server workstation. These specifications are also recommended for any additional client workstations running Objet Studio.

PolyJet Studio running on a 32-bit application can utilize only 4 GB of memory.

- NVIDIA® Quadro® Family—FX570, FX1700
- NVIDIA® GeForce® Family—6200 TurboCache™, 7300 GT, GTX 285
- Intel® Express Chipset—82915G/GV, 82910GL, Q965, Q963, Q35, Q45, Q43, 82852, 82855
- ATI Radeon™ HD 5670, HD 5970
- AMD Radeon™ E6760

⁵Most anti-virus programs can be used. Programs by vendors listed were tested in Stratasys labs.



¹ For systems using a KVM switch box to control both the built-in printer computer and the server workstation with same keyboard-monitor-mouse set: All-in-one computer, wireless mouse and wireless keyboard cannot be used.

²A 64-bit operating system is recommended, to utilize 8 GB of memory.

³The following graphics cards were also tested in Stratasys labs:

 $^{{}^4\!}For\,systems\,using\,a\,KVM\,switch\,box.\,If\,the\,server\,work station\,has\,a\,DVI\,video\,connector,\,a\,VGA\,adapter\,is\,needed.$

Electrical Requirements

The customer is responsible for ensuring that all tasks described in this section are performed by qualified personnel.

Power

A stable, reliable source of power is required. Power to the UPS (or printer) should be supplied directly from the main electrical panel. Other electrical outlets should not be connected to the line.

Printer power rating:

- 100-120 VAC, 50-60 Hz, 7 A, 1 phase
- 200-240 VAC, 50-60 Hz, 3.5 A, 1 phase

For information about actual power consumption, contact your Stratasys representative.


If the power at the facility does not support the above specifications, contact your Stratasys specialist.



Important:

The diagram below shows the required connection to the power socket. Make sure that the electrician sees this before installing the printer.

Figure 3 Connection diagram



Grounding

The printer is grounded through a single-phase, AC plug. Make sure that the AC outlet is properly grounded, in accordance with local electrical codes.



Circuit Breaker

A Type-C circuit breaker with the following specification is required on the power line (subject to the local electrical code).

Table 3 Circuit breaker

Voltage	Circuit Breaker
100–120 VAC	10 A
220-240 VAC	6 A

Residual Current Device (RCD)

The wall outlet must be connected to a residual current device (RCD).

Power Connection

The printer is shipped without a power cable, which is supplied during installation.

The following electrical outlets are required:

- · one outlet behind the printer
- three outlets close to the printer (for the workstation, monitor, and servicing equipment)

UPS (Uninterrupted Power Supply)

It is recommended that the printer is powered through a UPS unit, provided by the customer. If installed, the UPS ensures that—

- the quality of printing is not affected by power fluctuations from the mains.
- the printer can be programmed to perform "graceful shutdown" in the event of a power failure.

The UPS specifications are listed below.



Table 4 UPS requirements

Voltage ¹	Current	Power	Power Factor ²	Bridging Time	Interface
100–120 VAC	16 Amps	1500 VA	0.9	15 minutes	USB port ³ Compatible with Windows® 7
220–240 VAC	8 Amps		0.9	13 minutes	Command-line control ⁴

These UPS systems were tested at Stratasys and meet the above requirements:

- Eaton PW9130G3000T-220-240 VAC
- Eaton PW9130L2000T-XL-100-120 VAC

 $^{^4}$ Command-line control is necessary for the UPS software to execute a script in the printer software when shutting down.



¹Single-phase; 50/60 Hz

 $^{^2\!\}text{Defined}$ as the input-to-output ratio of the UPS.


 $^{^3 \}text{UPS}$ units that only connect to a serial communication port are not suitable.

Communication Lines

Local Area Network

A LAN communication cable is required if server/client workstations are connected to a local network, as shown in the following diagram.

Figure 4 Network installation



The connection to the local network should be established *prior to* printer installation.

Telephone

A telephone near the printer is recommended for general communication and service calls.



Environmental Conditions

Temperature and Humidity

The temperature and relative humidity around the printer must be maintained within certain limits. Peak conditions occur when the printer and the server workstation draw maximum electrical power, resulting in the heat dissipation listed in the table below.

Table 5 Heat dissipation (peak conditions)

	Heat Dissipation
Printer	760 W (2600 BTU/hr)
Server workstation	450 W (1530 BTU/hr)
Total	1210 W (4130 BTU/hr)

The room temperature and relative humidity should not exceed the limits listed in the table below.

Table 6 Room temperature and relative humidity specifications

	Range
Temperature	18°C to 25°C (64.5°F to 77°F)
Relative humidity	30%-70% non-condensing

Air Quality

The room ventilation system should change the air at least four times every hour.

Noise Level

The noise level at a distance of 100 cm (39.4 in) from all sides around the printer is less than 70 dB during printing. The printer does not generate impact noise.



Accessories and Utilities

Start-Up Kit

The printer is supplied with a start-up kit, which includes tools and accessories. These tools and accessories should be available during printer installation and operation.

Fire Safety Equipment

A gas-based fire extinguisher is recommended in case of fire in or near the system. Some other fire extinguishers are also acceptable, but liquid fire extinguishers should not be used. (Contact local fire authorities for specific recommendations.)



Materials Handling and Storage

Printing Materials

Printing materials should be stored indoors, in a dry area with adequate ventilation. The following table lists general requirements for transport, storage, inventory control, and disposal.

Table 7 Requirements for hazardous materials

Topic	Requirement
Storage	15°C to 27°C (59°F to 81°F)
Inventory control method	First In First Out (FIFO)
Disposal	In compliance with local regulations

These specifications are applicable for most printing materials. Requirements for handling and storing specific materials appear in the Material Safety Datasheet (MSDS) included with each material.



Note:

- Non-compliance with these recommendations might result in reduced shelf life.
- Disposal of all liquid and solid waste, cleaning cloths, gloves, and empty material containers must be done in accordance with local laws and regulations.

Cleaning Solvent

One liter of isopropanol (IPA) or ethanol (ethyl alcohol) should be available at all times for cleaning purposes.

The customer is responsible for ensuring that the material storage area complies with local regulations.



Site Preparation Checklist

A checklist is provided by your Stratasys representative listing all of the tasks described in this document.

Fill in the information requested in the checklist, and submit it to your Stratasys representative. An installation date will be scheduled after the checklist has been approved by Stratasys.





www.stratasys.com

HEADQUARTERS

7665 Commerce Way, Eden Prairie, MN 55344

- +1 888 480 3548 (US Toll Free)
- +1 952 937 3000 (Intl)
- +1 952 937 0070 (Fax)

1 Holtzman St., Science Park, PO Box 3496

Rehovot 76124, Israel

+972 74 745 4000

+972 74 745 5000 (Fax)



THE 3D PRINTING SOLUTIONS COMPANY

ISO 9001:2008 Certified

©2018 Stratasys Ltd. All rights reserved. Stratasys, Stratasys logo, PolyJet, Objet, Objet24, Objet30, Objet30 Pro, Objet30 Prime, Eden, Objet Eden260V, Objet Eden260V, Objet Eden260VS, Objet Eden350V, Objet Eden500V, Connex, Objet260 Connex1, Objet260 Connex3, Objet350 Connex3, Objet350 Connex1, Objet350 Connex3, Objet500 Connex3, Objet500 Connex3, Durus, Endur, Vero, VeroBlue, VeroBlue, VeroClear, VeroCyan, VeroDent, VeroDentPlus, VeroGlaze, VeroGray, VeroMagenta, VeroWhitePlus, VeroYellow, Tango, TangoBlack, TangoBlackPlus, TangoGray, TangoPlus, Digital ABS and Digital ABS2 are trademarks or registered trademarks of Stratasys Inc., registered in the United States and other countries. ULTEM is a registered trademark of SABIC or affiliates. All other trademarks belong to their respective owners. Product specifications subject to change without notice. For more information about Stratasys systems, materials and applications, call 888.480.3548 or visit www.stratasys.com