




LIST MACHINES		LIST POWER SUPPLY	
1	MANUAL PLAIN OF LOAD	A	POWER SUPPLY 3 PHASE + PE 220 V/AC 60 HZ- KW 6,00 - 30A
2	DOSING MACHINE		
3	FLOW PACK		
4	CHECK WEIGHYT		
5	CARTESIAN ROBOT LOADER	B	POWER SUPPLY 2 PHASE + PE 220 V/AC 60 HZ-KW 1,5 - 8A
6	STEPPER CONVEYOR		
7	CASE BOX MACHINE	C	POWER SUPPLY 3 PHASE + PE 220 V/AC 60 HZ - KW 3 - 15A
8	CARPET CONVEYOR		
9	WRAPPING BOX MACHINE	D	POWER SUPPLY 3 PHASE + PE 220 V/AC 60 HZ - KW 3 - 15A
10	SUPERIMPOSE BOX		
11	CASE CROSS BOX	E	POWER SUPPLY 3 PHASE + PE 220 V/AC 60 HZ - KW 3 - 15A
12	OVERWRAPPING CROSS	F	POWER SUPPLY 3 PHASE + PE 220 V/AC 60 HZ - KW 3 - 15A
13	ROLLER CONVEYOR		
14			POWER SUPPLY Conveyor electric pannel
15		G	POWER SUPPLY 3 PHASE + PE 220 V/AC 60 HZ - KW 3 - 15A
16			