




HEIDENHAIN

Programm-Einspeichern/Editieren

```
3 TOOL CALL 1 2 S1000
4 L X+0 Y+0 RR FMAX M3
5 L Z-10 R0 F9999
6 CC X+0 Y+8
7 C X+7.908 Y+6.787 DR+ RR
8 L X+10.538 Y+23.936 RR
9 CC X-29 Y+30
10 C X+10.591 Y+35.707 DR+ RR
11 L X+7.153 Y+59.553 RR
12 CC X+22 Y+61.693
13 C X+16.818 Y+75.77 DR- RR
14 CC X+12.5 Y+87.5
15 C X+12.5 Y+100 DR+
16 L X-12.5 RR
17 CC X-12.5 Y+87.5
```

BACK
HARD RESET

STOP
LOCK

STOP
EXT. FEED

STOP
HYD. LOCK

STOP
EINW.

Einführung