

440x600 HORIZONTAL X-NC-BS

Technical data



- It is a highly efficient automatic hydraulically controlled band-saw with multiple material feed.
- The band saw machine is designed for cutting in semiautomatic cycle perpendicularly as well as angularly.
- It enables angle cuts to the left (60 grades) and to the right (60 grades).
- The band saw machine suitable for cutting of steel constructions and profiles with a longstep feeder L=2000mm. The machine is constructed for automatic cutting of long bars.
- When the machine is cutting Automatic programm with angle cuts and with lengths shorter than (500mm), the machine automatically interrupts the automatic cycle and is waiting.
- It is suitable for serial production and thanks to its robust construction enables to cut wide range of materials including stainless steels and tool steels both profiles and full materials.

Control system:

- Machine is equipped with programmable automatic PLC SIEMENS SIMATIC S7-1200. Drive of band blade, movement of arm and movement of feeder are completely controlled and drive by SIEMENS technology.
- Colored touch display – HMI SIEMENS TP 700 COMFORT enable easy communication with operator.
- The machine enables to work with two modes:
- SEMIAUTOMATIC CYCLE: The machine cuts the material immediately in a semiautomatic mode. The operator uses the feeder of the machine for the manipulation with the material and for the exact feed of the material into the cutting zone. The movement of the feeder is realized by manual buttons or by GTO function. After starting GTO function the operator sets the position of the feeder, presses START button and feeder goes to the set position.
- AUTOMATIC CYCLE: the feeder feeds the material according to the set program. The operator sets the cutting program, machine realizes these programs, it is possible to make 1000 different programs. The part of one program is a complete setting of the cut: blade speed, feed speed, setting of an automatic regulation, setting of the height of the bar to be cut, setting of the length of the bar and number of pieces. The length and number of pieces it is possible to set in 20 lines, the machine feeds differently set lengths automatically.
- Regulation of cutting feed is realized by controlled system by the servo-motor and throttle valve hydraulics. Then is reached very precise cutting feed. Operator will input into program required cutting feed (mm/min) and bandsaw this cutting feed precisely set. Two basic regimes of automatic system regulation (ASR): ARP a RZP-2.
- RZP-2: cutting zones regulation. System enables to set of optimal shift speed (movement to cut) and blade speed in 5 different zones depending on blade position.
- ARP = System of the automatic regulation of the cutting feed rate depending on the cutting resistance of the material or blunting the blade.
- System offers two basic modes of ARP: BIMETAL and CARBIDE.
- BIMETAL mode is suitable for optimization of the cutting feed when cutting profiles by bimetal blades. The cutting feed is higher if the blade cuts sides of the profile. As the blade reaches the full material, the system reduces the cutting feed automatically so that teeth gap of the blade would not be filled.
- CARBIDE mode is suitable for cutting of full bars. If the blade is old (blunt), loaded is the cutting feed reduced Reaction time is slower than in mode BIMETAL.
- Safety module with autodiagnosics.

Construction:

- The machine is constructionally designed in that way, so that it corresponds to extreme exertions in productive conditions. A robust construction of machine includes vice allows to take advantage of bimetal blades maximally.
- The arm of the machine is robust, heavy weldment and it is designed so that a toughness and a precision of cut was ensured.
- The arm moves along two columns using a four row linear leading with a high loading capacity. Arm movement using two hydraulic cylinders.
- Drive pulley and tighten pulley are both metal castings.
- Arm uses the incremental encoder and the magnetic tape to evaluate a position over material and an end stop for setting the down position.

440x600 HORIZONTAL X-NC-BS

Technical data



- Main vice with divided jaw that clamps the material in front of as well as behind the cut. The jaws allow a safe grip. The optimization of the chip movement through the fixed jaw directly to the chip extractor.
- Jaws of the main vice move in steel leading using hydraulic cylinder. One jaw is longstroke (the movement by longstroke hydraulic cylinder), one is fixed.
- Regulation valves for setting a vice pressure in hydraulic system.
- Very rigid feeder is placed on the basement with rollers by the linear leading
- Feed step 2000 mm, Multiple feed (max. length 30m)
- Feeder movement is made using a linear guide, ball screw, toothed belt and servodrive
- The precision of the feeder positioning is adjusted by the Siemens frequency converter
- The incremental rotary sensor for feeder position indication is part of servodrive.
- Operator choose one from 5 feeder speeds.
- Indication of material in the feeder: optic sensor - it notices that there is a material in the feeder. If there is no material in the feeder, the signal reflects on the glass that is situated on movable jaw and it goes back to the sensor. The machine stops feeding and waits for another bar.
- There is a roller conveyer which supports material.
- The feeder clamping vice is a robust steel weldment. Jaws ensure safe clamping of the material.
- Jaws move on two rails of linear system thanks to hydraulic cylinder. One jaw is longstroke (the movement by longstroke hydraulic cylinder). Second jaw is shortstroke.
- Turn table is massive weldment. Turn table for angular cuts with milled leading parts of base. Turn table enables comfortable clamping of cutted material.
- Turning of the table for angle cuts is ensured by the hydraulic cylinder and the rack and pinion gear, hydraulic fixing at turn. RoTo function (rotate to position) with the automatic setting of the desired position.
- The angles indicated on the digital display on the control panel. Reading of angle by incremental sensor and magnetic tape.

Basic equipment of the machine:

- The blade leading in guides with hardmetal plates and leading bearings and along cast iron pulleys.
- The blade is sloped regarding the level of the vice => higher performance when cutting, profiles, longer bladeflife, higher performance when cutting full materials.
- There is a guide situated on the firm beam on the drive side. On the tightening side there is the guide situated on the moving beam.
- The guide beams of the blade are adjustable in the whole working range. A guide moving is connected with a vice-jaw movement so that to achieve the minimum distance of the guide and material. That is why it is not necessary to set the position manually.
- The guide beam of the blade is placed in linear rails (2 linear rails and 4 bearings) with high bearing capacity.
- The saw-band is equipped with a guard, which protects the operator from millings and cutting emulsion.
- Hydraulic tightening of band.
- Automatic indication of blade tension.
- A passive driven cleaning brush for perfect cleaning and function of blade by roller.
- Pulley drive the saw blade is solved by worm gear box with maintenanceless oil filling. Three-phases electromotor with double winding, with a frequency converter for a fluent regulation of the blade speed from 20 to 100 m/min. Sturdy flange with shaft. Termoprotection of engine.
- The cooling system for emulsion, leaded to the guides of the blade and by LocLine system directly to the cut groove.
- Massive base with a tank for chips. Base is designed for manipulation manipulation with machine by pallet truck and also by any hight lift truck or by crane.
- Indication of blade tightening and opening of the cover.
- Controlling 24 V.
- Machine is equipped with hydraulic system which controlles all functions of the machine. It pushes the arm to cut, pulls up the arm, opens and closes vices, turnins the turntable for angular cuts.

440x600 HORIZONTAL X-NC-BS

Technical data



Basic accessories of machine:

- RTS - pressure control vice.
- Two massive cylinders support material to be cut. Movable by linear leading. Placement at the output side.
- Spray gun for chip rinsing
- Lighting of workink space.
- Band saw blade.
- Set of spanners for common service.
- Manual instructions in eletronic form (CD).

Operating cycle:

After starting the machine, vices clamp after starting the machine, the machine makes the cut by a set speed, the cutting zone in the down position of the arm is released - the longstroke jaw of the firm vice open, the feeder moves the material to the firm vice, the arm lifts up to the set upper position. The material is moved by the feeder – periodic regime (feeder moves between zero position and the position of the set lenght of feed) or consecutive regime (feeder moves to the limit position and clamps the material and feed it to the cut consecutively). The main vice clamps the material, the vice of the feeder is still closed and the whole procedure repeats. The operator only loads the material and removes the cut material. It is possible to regulate the cutting speed of the arm and the blade speed during cutting.

440x600 HORIZONTAL X-NC-BS

Technical data



Cutting parameters						
	0°					
	470	475	330	475	305	x
	250*	180*	130*	180*	130*	x
	610x410	490x415	320x410	495x415	305x425	610x255

- Recommended values. Recommendations of band blade producers are to be followed when choosing to cut full material, their dimensions are limited by available size of the teeth for the specific type of the band.
- Cutting of the bundle without upper vice HP. HP = accessory for additional price. The cutting parameters are limited when using

ATTENTION:: In case the machine is with heating (option), the possible angle to the right is 45° only. It is necessary to remove heating covers before turning the bigger angle than 45°, but pay the strong attention to avoid of collision!!

Cutting parameters		
the shortest cutting	mm	3
the smallest divisible diameter	mm	10
the shortest rest during one cut	mm	30
the shortest rest in automatic cycle (angle 90°)	mm	140
one feed step of the material Min	mm	3
one feed step of the material max	mm	2000
multiple feed	mm	19 999

Performance parameters		
drive of the blade	kW	4,0
drive of the hydraulic aggregate	kW	0,75
pump of the cooling emulsion	kW	1,5
Drive of the feeder	kW	2,2
total input	kW	6,8
cutting speed – fluently set	m/min	20-100
diameter of the blade	mm	6060x34x1,1
The blade is sloped regarding the level of the vice	°	6
electric connection		3x400V, 50 Hz, TN-S

Working movements	
Feed of the Frame to the cut	Hydraulically
Feed of the material	Electromotor + gearbox
Clamping of material	Hydraulically
Bend tension	Hydraulically
Cleaning of the blade	Cleaning brush driven by a pulley

Saw dimensions							
Lenght		Width	Height		Height of the table		Weight
Lmin]	[Lmax]	[B]	[Hmin]	[Hmax]	[V]		(kg)
2900	3510	4600	2140	2390	810		3835