

零件代号

借(通)用件登记

描图

描校

旧底图总号



底图总号

签字

日期

Technical requirements

1. At least 1m away from obstacles around the whole machine.
2. The whole machine should be far away from the source of vibration.
3. The flatness of the place where the whole machine is in place should not be greater than 5mm.
4. The access voltage of the whole machine fluctuates within $\pm 5\%$.
5. Choose one of the fan and the dust collector, and the fan and air source can be placed in a position that does not affect the use.
6. The voltage stabilizer, air compressor, drying machine and dust collector are non-standard equipment, which are selected by customers. If they are selected, they can be placed according to the drawing.
7. The safety light curtain is non-standard equipment, which is optional for customers.
8. The location of the equipment in this layout drawing is for reference only, and the actual placement depends on the actual situation on site.
9. If other optional external devices are involved, please communicate with the technical department for the location.

						Equipment layout diagram				
标记	处数	分区	更改文件号	签名	年、月、日				Fiber Laser Cutting Machine	
设计			标准化		2023.02.17	阶段标记	重量	比例		
制图								1:100	OR-TG6020	
审核						共 张 第 张				
工艺			批准							